

Douglas County Surveyor's Record of  
Government Corners Renewed

26 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91801

Tony Hostetter  
For: Weyerhaeuser Co.  
Nov, 1998  
M131-5

87

1/4 Corner for Sections 23 & 24

Found - 1971 BLM brass cap as described in Vol. 17 Pg. 15211.  
40" Fir stump, Weyco tag & "W" nail, bears N.20°E., 57.2 ft.  
16" Fir stump, face evident, BT tag, bears N.29½°W., 31.9 ft.

New Accessories -

12" Alder, bark scribed "S24 1/4 BT" bears N.64°E., 24.1 ft.  
16" Hemlock, scribed "S24 1/4 BT" bears S.65°E., 43.7 ft.  
10" Alder, bark scribed "S23 1/4 BT" bears S.7°W., 1.2 ft.

See BLM Resurvey v. 54 pg 21036

1/4 Corner for Sections 13 & 24

Found - 1971 BLM brass cap as described in Vol. 37 Pg. 15212.  
16" Fir, possible face, bears S.11°W., 16.0 ft.  
15" Fir, face evident, BT tag, bears N.38°W., 18.7 ft.

New Accessories -

12" Fir, scribed "S24 1/4 BT" bears S.46°E., 13.0 ft.  
11" Fir, scribed "S23 1/4 BT" bears N.82°W., 5.8 ft.

Note - Measured dist. to new accessories is to 6" spike in root collar (below face).

88

89

1/4 Corner for Sections 24 & 25

Found - 1971 BLM brass cap as described in Vol. 37 Pg. 15209.  
32" Fir, face evident, bears N.26°E., 41.3 ft.  
9" Fir, Weyco tag & "W" nail, bears N.46°E., 4.6 ft.  
16" Fir, possible face, bears S.68°W., 11.9 ft.

New Accessory -

10" Fir, scribed "S24 1/4 BT" bears N.77°E., 21.0 ft.

Note - Measured dist. to new accessory is to 6" spike in root collar (below face).

90

1/4 Cor. Secs. 20 & 29

Found - 1972 BLM BC as described in DSCO records pg. 14871.  
33" Fir, face evident, BLM BT, bears N.43°E., 54.1 ft. to center.

New BTS - 16" Alder, bark scribed "S20 ¼ BT", WEYCO tag, bears N.20°E., 18.2 ft. to spike placed in root collar below scribing.  
26" Fir, scribed "S29 ¼ BT" WEYCO tag, bears S.20°W., 41.1 ft. to spike placed in root collar below scribing.  
22" Fir, scribed "S29 ¼ BT" WEYCO tag, bears S.66°W., 11.6 ft. spike placed in root collar below scribing.

Sec. Cor. Secs. 19, 20, 29, & 30

Found: No evidence of 1972 BLM brass cap or BTs described on pgs. 14866 of DCSO recs. However, blazed lines were found in 4 directions from the corner & used to establish approx. location of 1972 mon. (Note: this area has been subject to landslide & flood damage.) From this approx. point, steel fence post was found buried lying horizontally @ N.70°W., 8 ft. away. There is also a large rock @ N.60°E., 24 ft. more or less buried under several large logs which may be the orig. bearing object described by the BLM in 1972. The ¼ corner between secs. 20 & 29 measured by 1972 BLM retracement survey to be 40.40 ch (2666.40 ft.); N.88°45'W., from this sec. corner, was found to be 2664.92 ft. from the approx. corner position (as measured by total station traverse).

In order preserve this approx. location, which may be the best available of an orig. corner position, the following BTs were established:

20" Alder, bark scribed "S21 SW BT" WEYCO tag, bears N.8°E., 29.4 ft. to spike placed in root collar below scribing.

22" Alder, bark scribed "S21 SW BT" WEYCO tag, bears N.20°E., 48.3 ft. to spike placed in root collar below scribing.

"X" marked in sandstone bluff, bears S.70°W., 22.7 ft.

91

91

Tony Hostetter  
For: Weyerhaeuser Co.  
May 2001  
C.S. File 65/37-12 & 13