

**Douglas County Surveyor's Record of  
Government Corners Renewed**

27                      T. S.                      3                      R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Mark Heimburger  
For; Glide Lumber  
11/96  
M 126-11

**161**

Center 1/4 Cor. sec. 27  
Set - 5/8" x 30" iron rod w/plastic cap mkd:"AA SURVEYING INC."  
from which a:  
7" Fir bears N.20°W., 17.3', scribed "C $\frac{1}{4}$  S27 BT"  
8" Fir bears N.57°E., 25.7', scribed "C $\frac{1}{4}$  S27 BT"  
11" Fir bears S.76°E., 30.5', scribed "C $\frac{1}{4}$  S27 BT"  
7" Fir bears S.35°W., 20.0', scribed "C $\frac{1}{4}$  S27 BT"

Douglas County  
Surveyor's Office  
Randall Smith  
Stephen Flause  
Dec. 9, 1996  
C.S. File 65/9-35

**162**

1/4 Corner for Sections 28 & 27  
Found - 3 $\frac{1}{4}$ " dia. brass cap on a 2 $\frac{1}{2}$ " O.D. iron pipe, protrudes 2"  
above ground (1958 B.L.M.)  
Accessories Found -  
40" now 40" dia. down Cedar with a fully healed single  
blaze, roothole agrees with rec. "S.31°E., 51.5 ft."  
(1958)  
18" now 22" dia. 2 ft. high D.Fir stump with a fully healed  
single blaze, bears N.16°W., 29.0 ft. (1958)  
New Accessories -  
11" dia. D.Fir double blazed and scribed "1/4 S27 CS BT"  
bears S.74°E., 5.9 ft.  
15" dia. D.Fir double blazed and scribed "1/4 S28 CS BT"  
bears S.03°W., 13.9 ft.  
6" dia. W.Fir double blazed and scribed "1/4 S28 CS BT"  
bears N.03 $\frac{1}{2}$ °W., 20.9 ft.  
18" dia. D.Fir double blazed and scribed "1/4 S28 CS BT"  
bears N.65°W., 1.9 ft.

Douglas County  
Surveyors's Office  
Randall Smith &  
Stephen Flause  
Jan. 13, 1997  
C.S. 64/71-7

**163**

Sec. Cor. 27, 28, 33, & 34  
Mons. Fd- 3 $\frac{1}{2}$ " dia. Brass cap on a 2 $\frac{1}{2}$ " O.D. Iron pipe protrudes 5"  
above ground.  
3/4" I.R. with "+" on top, bears N.24°E., .8'  
1/2" I.P. found in 1958 BLM Survey not visible  
US CADASTRAL SURVEY  
T27S R3W  
S28|S27  
S33|S34  
1958  
BUREAU OF LAND MANAGEMENT  
Bt's Fd.- 49" Dia. 80' high D.Fir snag, with bark scribing visible,  
bears S.47°W. 32.5' (rec. S.45°W., 29.7' Dist falls short  
of BT) OBT.  
36" Dia. Cedar, with a healed blaze, bears N.30°W., 25.3'  
(Rec. N.30°W., 23.8' Dist. fits well to face ) OBT.  
No other OBT's found  
27" Dia. Cedar, with a fully healed single blaze, bears  
S.32 $\frac{1}{2}$ °W., 41.5'. (Rec. S.35°W., 39.6' Dist. falls  
short of BT 1958 BLM).  
27" Dia. 20' high Cedar snag, with an unhealed sing blaze,  
scribing visible "T27S R3W S28 BT", bears N.32°W.,  
53.5' (agrees with rec. 1958)  
No other 1958 BLM BT's found  
Per orig. notes- 14" Fir S.35°E., 11.2' per C.S. 35/19, 16" Yew S.  
35°E., 11.2', we find a 16" Dia. Yew with a  
partially healed blaze, no scribing visible,  
bears S.44°E., 11.2' OBT?  
New Accessories - 11" Dia. D.Fir, double blazed and scribed "T27S R3W  
S34 CS BT", bears S.88°E., 34.9'.  
12" Dia. D.Fir, double blazed and scribed "T27S R3W  
S27 CS BT", bears N.55 $\frac{1}{2}$ °E., 34.9'.