

Douglas County Surveyor's Record of
Government Corners Renewed

27

T. S.

4

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Byron
M. Godfrey
C. Putnam
July 13, 1961
C. S. File
No. 49/130

South $\frac{1}{4}$ Corner to Section 36.
Found - Orig. 8", now 16" Cedar Snag S.35°W. 23.1 ft. We open old cut and find scribing "T". We also find good scribing on old chip " $\frac{1}{4}$ " S". No trace of Orig. N.W. BT. found.
Set - Brass Cap at Corner & under 36" Log Mkd: South $\frac{1}{4}$ S36 T27S R4W, County Surveyor's Office, 1961.
New BT's: 10" Cedar bears N. 9°W 9.7 ft. scribed S1/4 S36 CS BT.
12" Cedar bears N. 59 $\frac{1}{2}$ °E. 49.0 ft. scribed S $\frac{1}{4}$ S36 CS BT.

61

J. Byron
M. Godfrey
C. Putnam
7/14/61
C. S. File
No. 49/67

Corner ^{R4W} $\frac{S36/S31}{S6}$ T27S
Found - All found Orig. BT's. The SW & NW Orig. BT's. show good scribing. All check record. Stake at Corner.
New BT's: 20" (Orig) Laurel bears N. 22°W. 12.5 ft. scribed S36 T27S R4W CSBT
32" (Orig) Laurel bears N. 50°E. 13.0 ft. scribed S31 T27S R3W CS BT.

62

James W. Byron, Deputy
Dale McFarland
Jim. Powell
Sept. 14, 1961
C. S. File No. 49/67

Corner to Sections 35 and 36 only.
Found - Orig. 6", now 30" R. Fir S. 57°W. 21.8 ft. - Orig. 24", now 30" R. Fir N. 58°W. 27.7 ft., shows good bark scribing. N.E. & S.E. BT's., now 30" Firs, show good bark scribing. Now down slope about 50'. Stump holes check record bear. & dists. N. E. BT. not Maple.
Set - Brass Cap Mkd: County Surveyor's $\frac{S35/S36}{T28S}$ T27S R4W
Office, 1961
New BT: 16" R. Fir bears N. 47°E. 57.3 ft. scribed S36 T27S R4W CS BT.

63

$\frac{1}{4}$ Corner to Sec. 33, T27-4W. & Sec. 4, T28-4W.
Found - $\frac{3}{4}$ " I. P. at corner & under E.W. Fence. We also find both BT's. as recorded by Frear, 1918. We open N.W. BT. & find good scribe marks. Both BT's. now stumps.
New BT's: 8" R. Fir bears N. 16 $\frac{1}{2}$ °E. 75.7 ft. scribed $\frac{1}{4}$ S33 CS BT.
9" Laurel bears N. 23 $\frac{1}{2}$ °W. 45.5 ft. scribed $\frac{1}{4}$ S33 CSBT.
No trees near to South.

64

By James W.
Byron, & Crew
C. S. File
No. 49/28

Township Corner $\frac{S25/S30}{S36/S31}$ T27S R4W R3W
Found - 1917 Brass Cap at Corner, All BT's, now dead.
New BT's: 5" Hemlock bears N. 4°E. 92.0 ft. scribed S30 CS BT.
7" Hemlock bears S. 72°W. 94.3 ft. scribed S36 CS BT.
~~SEE REN. NO 83 FOR BT. NOT RECORDED~~ Sept. 18, 1962

65

Set by
Germond
1908 or
1909

$\frac{1}{4}$ Cor. South Side of Section 36, T26-4W.
Stake White Oak 4" x 4" x 3'. Mkd: Witness Trees as follows:
W. Oak 24" S. 10°E. 115 lks.
Red Fir 6" N. 54°26'E. 109 lks.

66

H. Eppstein, Co.
Surv.
Feb. 1934

$\frac{1}{4}$ Corner on Township Line Sec. 3, T27-4W. & Sec. 34, T26-4W. #138
Set - Star Auto Axle for corner from the Old BT., namely 15" White Oak N. 10°E. 96 links. Other BT. gone.
Marked: 8" E. Walnut bears S. 60°15'E. 239 ft. Mkd: CS $\frac{1}{4}$ S BT.
1/27/71 - FOUND O.K. J.W. Byron c.s. 56/1

67

N. E. Richardson
Wit: Milo
Godfrey
L. Kershner

Township Corner - N. E. Cor. Section 1, T27-4W.
Reset from 3 Old BT's., badly deteriorated.
Set - 1 $\frac{1}{2}$ " I.P. with Brass Cap 24" in ground Mkd: T26S $\frac{S36/S31}{S1/S6}$ R4W T27S R3W
36" Fir bearing S. 6°E. 543.8 feet
10" W. Oak bears S. 81°W. 195.8 feet
30" W. Oak bears N. 15 $\frac{1}{4}$ °W. 231.5 feet. County Surveyor's Office
January 7, 1947

68

(Duplicate of #57)