

Douglas County Surveyor's Record of
Government Corners Renewed

T 27 T. S. R 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

154

Section corner for Secs. 6, 5, 7 and 8.
Found - An orig. "Y" Oak, 10" now an 18", 20 ft. snag bears N.53°E.,
48.2 ft. We open this tree to find scribe "5W 27S" reverse
scribing "R5W T27S B" and notch.
An orig. 18" "Y" Oak, now a 22", 12ft. high rotted snag, bears
S.52 1/2°W., 44.9 ft. (Rec. S.60°W.). We partially open
blaze to find scribing "BT" and "axe notch".
An orig. 12" Oak, now a rotted and down tip out, size indeter-
minate bears N.11 1/4°W., 51.5 ft. to roothole.
An orig. 10" W. Oak, now a 22", bears S.85 1/2°E., 159.1 ft.
(Rec. S.82 1/2°E., 155.8 ft.) We do not open tree.
Set - A 1" x 36" I.P. with brass cap stamped "Douglas County Surveyor's
T27S R5W S6 S5 S7 S8 1979, at position from orig. BT's.
New BT's- A 10" B. Oak 15" at base, (two trunk tree) scribed "T27S R5W
S7 CS BT" in a double blaze bears S.84°W., 7.3 ft. dist.
An 8" B. Oak scribed "T27S R5W S6 CS BT" bears N.23°W., 16.8 ft.
A 12" P. Pine scribed "T27S R5W S5 CS BT" bears N.9 1/2°E., 67.8 ft.
12/20/79

Doug. Co. Surveyors
Office
L.E. Monrean
K. Reed;
M.S. Means
Dec. 20, 1979
C.S. 60/34

155

1/4 Corner to Secs. 19 and 30
Fd. - 1" Iron pipe with brass cap properly mkd. protruding 1.1 ft.
above the ground. REN. #67
An orig. 8" dia. W. Oak now 31" with previously chopped open
blaze visable scribe "BT" bears S.65 3/4°E., 118.8 ft.
A 12" dia. W. Oak, now 13" with well healed double blaze bears
S.55°W., 47.4 ft. (REN. #67)
A 10" dia. W. Oak, now 11" with well healed double blaze bears
N.28 1/2°E., 29.1 ft. (REN. #67).
New BT's - An 18" Dia. W. Oak scribed "1/4 S19 CS BT" in a double blaze
bears N.71°W., 51.7 ft.
Note - Corner lies approx. 5.5 ft. south of down E - W fence.

Doug. Co. Surveyor's
Office
Karen Reed
Terrie Plouff
May 1980
C.S. 60/34

156

Section corner for Secs. 6 and 7; and Secs. 1 & 12 of T.27-6
Found - A 1967 DCSO brass cap on a 1" x 36" I.P. properly stamped. Ren. #116
set firmly in the ground protruding 0.1 ft. above ground.
A iron bolt with a 1" square head set along the NW side of the cap.
No original evidence found.
A 20" White Oak, now 26" bears N.46°W., 132.0 ft. with well healed
upper blaze & previously chopped lower blaze, now rotted.
A 12" White Oak now 20" bears N.40°E., 76.5 ft. to center, 75.9 ft.
to face. (Rec. 85.6 ft. changed to 75.6 ft. Ren. #38) with
well healed single blaze.
Set - Left brass cap and bolt in place as they apperared undisturbed.
New Accessories:
A 5/8" x 30" iron Rod with alum. cap stamped "BO 1" bears
S45°E., 30.0 ft. buried 2 inches below ground.
A 5/8" x 30" iron rod with alum. cap stamped "BO 2" bears
S.45°W., 30.0 ft. buried 2 inches below ground.
No trees available to the south at reasonable dist. Corner lies in
open field approx. 64.0 ft. south of Newton Creek.
9/30/80

Stephen Flause
Deputy, Doug. Co.
Surveyors Office
Karen Reed
Teresa Buley
Sept. 30, 1980
C.S. 61/11

CORNER REPORT ONLY.

Section corner for Secs. 30 and 31; and Secs. 25, 36 of T.27-6.
Found - a 2" x 2" Angle iron fence post 5 ft. tall set in concrete -
4 way fence junction. (no record).
14" B. Oak bears S.43°W., 95.4 ft. Ren. #75
12" W. Oak bears N.84°E., 42.0 ft.
The 5/8" iron rod set per M42-50 (Garrett) is missing.
(This corner used as tie for M79-75)

Burton Holt
For: Mel Mendenhall
March 1981
M 79 - 75

pd 8/90
M112-12

3/81