

Douglas County Surveyor's Record of
Government Corners Renewed

28

T. S.

3

R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 97501

Gerald V. Nygren
LS #1035
For: Forest Service
March 1988
C.S. 63/69

South 1/4 Cor. for Section 13.

161

Found - A 1" galv. iron pipe with 2 1/2" brass cap flush with ground marked
"COUNTY SURVEYORS OFFICE T28S 1/4 S13 R3W, 1962."
A brass cap, 1/4 for sec. 24, bears N89°34'E, 12.24 ft.
- A 8" Yew, bears N58°E, 6.1 ft. (vis. scribe) SEE REN#89
14" Yew snag, bears S55 1/2°W, 27.1 ft. (vis. scribe)
34" Hemlock stump, bears N84 1/2°W, 11.0 ft. (vis. scribe)
New BT - A 13" Hemlock, bears N63°W, 35.8 ft., scribed "T28S R3W 1/4 S13 BT"
with brass washer stamped "RLS 1035" nailed flush to the
lower end of the blaze..

Closing Corner for Sections 23 and 24 only.

162

Found - 1" iron rod, firmly set, projecting 30" above a 2 ft. mound
of stone with a 2 1/2" alum. cap mkd "U.S.P.C. Property Corner Do
not Disturb | 13 R.E. 4287" (Shrum, Ren. #16)
23 24
Orig. BT, a 24" D. fir stump, S.52°W., 42.2 ft. (Rec. 40.92 ft.) with
a healed blaze.
A 16" D. fir, N.85°E., 64.5 ft. with scribe marks "S13 RE4287 CC"
visible on a partially healed double blaze. Ren. #16
A roothole, S.24 1/2°E., 58.8 ft. with a downed 15" D. fir alongside
with a partially healed double blaze. Ren. #16
A 6" Yewwood, S.01 1/2°W., 33.1 ft. (Rec. 33.6 ft.) with scribe marks
"S23 RE4287 CC" visible on a partially healed double blaze. Ren. #16
Set - I add a 3 ft. dia. mound of stone to the found monument which now
projects 20".
From which: at the true closing corner point per M70-36, I set a 6 ft.
steel fence post, driven 2 ft. in the ground as a guard post,
S.0 1/2°E., 2.1 ft. with Forest Service signs #54-2 & 54-4 attached.
New BT - A 5" hemlock, S.30°E., 26.5 ft. scribed "T28S R3W S24 CC BT" on a
single blaze with a 3/4" dia. brass washer, stamped "LS1181",
nailed flush to the base of the blaze.
To Reach - 2.2 mi. past the end of pavement on Cavitt Creek Rd. No. 25, turn
west onto rd. #28-3-15 (Champion Rd. #CC900). Drive 1.9 fi. and turn
left onto Rd. #28-3-11 (CC920). Drive 2.8 mi. & turn left onto
Forest Rd. No. 1800-127. Drive 0.2 mi. to the sec. line crossing.
The corner is approx. 150 ft. west of the road at the culvert.
Magnetic declination is 20° east.

Maurice E. Farr
L.S. #1181
U.S. Forest Service
March 17, 1988
C.S. 63/73

3/17/88

North 1/4 Corner for Section 24 only.

163

CORNER REPORT ONLY

Found - 2" iron post firmly set, projecting 2" above the ground with a 2"
diam. brass cap attached. See Ren. #140
16" Hemlock stump, S.19°E., 5.5 ft. with scribe marks "N 1/4 S24"
BT visible on partially healed double blaze with a 7/8" diam.,
brass washer stamped "LS 934" nailed flush to base of lower blaze.
12" Hemlock stump S.31°W., 17.7 ft. with scribe marks "N 1/4 S24 BT"
visible on partially healed double blaze.
Brass cap for 1/4 corner Sec. 13 only bears West 12.2 ft.
A steel fence post projecting 4 ft. above the ground as a guard post
bears East 4.0 ft. with Forest signs #54-2 and #54-9 attached.

No new monument or bearing trees established.

Corner is at North edge of recent clearcut on a flat. To reach, 2.2 mi.
past the end of the pavement on Cavitt Creek Rd. No. 25, turn west onto
Rd. #28-3-15 (champion Rd. #CC900) Drive 1.9 mi. and turn left onto Rd. #
28-3-11 (CC920) Drive 2.8 mi. and turn left onto F.S. Rd. No. 1800-127.
Drive 0.9 mi. and turn left onto F.S. Rd. No. 1800-126. Drive 0.2 mi., turn
left onto F.S. Rd. No. 1800-120. Drive 0.8 mi. to section line crossing.
Corner is 550 ± ft. west of Rd. #120.

3/17/88

1/4 Corner for Section 13 only.

164

Found - A 2 1/2" I.P. with brass cap extending 8" above ground mkd. RLS 1005
T28S R3W 1/4 S13 | T28S R2W 1980. (Rec. per Ren. #148 and M83-19
says cap mkd. RLS 1654).
A 7" hemlock bears N.40°W., 10.1 ft. - visible scribing.
A 9" madrona snag bears S.85°E., 7.2 ft. - visible scribing.
New BT - A 5" cedar bears N.74°E., 11.3 ft. scribed "X BT". A 1/2" brass
washer was set in BT face marked "LS 1035".

Bearing tree and monument signs were placed on all BTs without them and a
6" red band and face blazes were painted on all bearing trees. 12/12/88

Gerald V. Nygren
LS 1035
For: USFS
Dec. 12, 1988
C.S. 63/92