

Douglas County Surveyor's Record of
Government Corners Renewed

T 28

T. S.

R 7

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

248

1/4 Corner for Sections 16 and 17
Found - 1" I. pipe. Ren. #186
24" W. Oak, S.88 1/2° E., 33.8 ft.
19" W. Oak, S. 51° W., 40.0 ft. mkd. as per M 32 - 76.
Set - 5/8" x 30" iron rod mkd. "Baughman Tech. Serv."
New BTs - 24" W. Oak, S.78 3/4° E., 34.8 ft. (scribe visible)
19" W. Oak, S.41 3/4° W., 44.2 ft. (scribe visible).
Set monument bears N 4°38'13"W., 7.77 ft. from found I.P.

249

1/4 Corner for Secs. ⁹ and 16.
Found - 2 1/2" I.P. with BLM brass cap
20" D. fir, N.64°E., 24.4 ft. (Rec. N.77 1/2°E., 25.1 ft.)
8" D. fir, S.36°E., 33.4 ft.
Set - 5/8" x 30" Iron rod mkd. "Baughman Tech. Serv."
20" D. fir, N.58°E., 20.1 ft. (Healed blaze.)
8" D. fir S.30 1/2°E., 32.1 ft. (healed blaze.)
Note - Set iron pipe bears N.73°46'16"E., 4.52 ft. from found B.C.

250

1/4 Corner for Sections 15 and 16.
Found - 2 1/2" I.P. with BLM brass cap.
6" W. fir, S.71°E., 56.1 ft. (scribe visible.)
14" Myrtle, N.17°W., 47.7 ft. (scribe visible.)
Set - 5/8" x 30" iron rod mkd. "Baughman Tech. Serv."
BTs - 6" W. fir, S.73 1/2°E., 54.6 ft.
14" Myrtle, S.16 3/4°W., 51.3 ft.
Note - Set iron pipe bears S.3°58'32"E., 3.64 ft. from found brass cap.

251

Center 1/4 Corner for Section 16.
Set - 5/8" x 30" Iron rod mkd. "Baughman Tech. Serv."
New BTs - 20" I. Cedar, S.0 3/4°W., 36.7 ft. scribed "C 1/4 S16 BT".
11" D. fir, N.43°W., 35.4 ft. scribed "C 1/4 S16 BT".

252

Section corner for Sections 16, 17, 20 and 21.
Found - 1" I. Pipe. Ren. #184
11" W. Oak, N.77 1/2°W., 31.7 ft. (healed blaze)
13" Oak, N.33°E., 9.5 ft. mkd. as per M 32 - 76.
Set - 5/8" x 30" I. rod mkd. "Baughman Tech. Serv."
BT's - 26" D. fir, N. 10 3/4°E., 192.2 ft. (scribed "T28S R7W S16 BT".
11" W. oak, S.69 3/4°E., 15.7 ft. scribed "T28S R7W S21 BT"
11" W. Oak, S.53 1/4°W., 16.4 ft.
15" D. fir, N.65 1/2°W., 63.5 ft. scribed "T28S R7W S17 BT".
Note - Set iron pipe bears N.46°15'18"W., 24.86 ft. from found I.P.

253

1/4 Corner for Sections 16 and 21.
Found - 1" Iron pipe. Ren. #185
17" D. fir, N.29°W., 13.0 ft. (healed blaze)
16" D. Fir, S.34°W., 13.5 ft. (healed blaze.)
Set - 5/8" x 30" Iron rod mkd. "Baughman Tech. Serv."
BTs - 17" D. fir, N.29 1/4°W., 5.6 ft.
16" D. fir, S.12 1/2°W., 17.7 ft.
Note - Set iron pipe bears N.30°02'17"W., 7.24 ft. from found I.P.

June 1984

254

Center 1/4 Corner for Section 23
Found - 3/4" Iron pipe protruding 8" from ground, firmly set. Ren. #237
New BTs - 14" D.B.H. D. Fir scribed C 1/4 S23 CS BT on a double blaze,
bears N.20 1/2°E., 4.9 ft.
10" D.B.H. D. fir scribed C 1/4 S23 CS BT on a double blaze,
bears N.54 1/2°W., 11.7 ft.
Note: Monument lies approx. 20 ft. NE of top of cut bank, approx. 800 ft.
SE of end of county maintained portion of Swan Hill Rd. #122.

Glenn Baughman, L.S. #536
For: Glide Lumber Products
June 1984
RM 3 - 62
C.S. 58/144 narrative

Stephen Flause
R. W. Smith
Doug. Co. Surveyors
Office
July 26, 1984
C.S. 62/18