

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 8 R. W. W. M.

H. L. Eppstein Co. Sur.
Wit.
Harley Johnson
B. A. Lane
G. C. Seller
Mar. 4, 1930
CS 19/58

Cor. of 10, 11, 14 and 15 continued
Marked the following trees
Red Fir 12" dia. bears N.56°30'W., 86.3 ft.
No other trees near in other sections.

CORNER NO. 29

1

Arthur Boyer
Wit.
Ralph Heater
Oct. 22, 1934
CS 14/77

SECTION CORNER BETWEEN 11, 12, 13 and 14.
Set post for corner from old B.T.s. Namely
A Fir S.W. and an Oak N.E.
Marked
Fir 5" dia. bears N.39°W., 52.0 ft. for witness tree
No other tree in the other Sections near.

SEE CORNER NO. 64

2

Arthur Boyer
Wit.
J.M. Weaver
B.W. Garney
Elmer Bushnell
Frank Kiehn
April 27, 1936
CS 23/41

1/2 CORNER BETWEEN SECTIONS 35 and 36.
Renewed from Original trees. Set 1" Galv. Pipe and
marked the following trees
White Oak 18" dia. (new tree) S.73°30'E., 108.6 ft.
Black Oak 36" dia. (new tree) S.57°00'W., 42.0 ft.
Original trees dead and about ready to fall.

SEE CORNER NO. 130

3

Arthur Boyer
Wit.
Richardson
P.D. Wolford
June 9, 1936

1/2 CORNER BETWEEN SECTIONS 34 and 35.
Renewed from original trees. Set a 3" x3" Cedar Post
and marked the following new trees
White Oak 18" dia. bears S.51°E., 35 ft.
Black Oak 30" dia. bears N.21°W., 49 ft.
(Original B.T.'s Rotten heart in tree to S.E. and dead
wood in stump-hole of B.T. to S.W.)

SEE CORNER NO. 44

4

Ben B. Irving
D.C.S.
Wit.
Richardson
Harmson
Jan. 25, 1939
CS 15/14

1 CORNER BETWEEN SECTIONS 33 and 34.
Set from Original 5" Oak B.T. S.86°E., 87 lks., which
is half dead. Tree S.61°W., is entirely gone. Set 1" torque
rod, steel, 30" length for corner from which
White Oak 30" dia. bears S.27°E., 104.0 ft.
White Oak 18" dia. bears S.39 1/2°W., 217.5 ft. - Fd. 4/78-1170-9

SEE CORNER NO. 65

5

Arthur Boyer
D.C.S.
Wit.
Richardson
Harmson
Jan. 25, 1939

1 CORNER BETWEEN SECTIONS 15 and 22.
Set 3" Fir stake for corner from original 16" Chinouapin
B.T. which bears S.38°W., 6.1 from corner. Other trees
gone. Marked following bearing tree which bear from corner
as shown
"Y" Fir 48" dia. bears N.74°W., 11.0 ft.
Red Fir 30" dia. Bears S.66°E., 13.6 ft.

SEE CORNER NO. 13143

6

Arthur Boyer
Wit.
Fred Kiehn
Elmer Bushnell
Oct. 7, 1939
CS 14/55

1/2 SECTION CORNER BETWEEN SECTIONS 31 and 36. (West side
of section 31)
Set a 4" square Fir post for the corner, scribed 1/2 S.
on the S. face, S.31 on E. face, S.36 on West face and C.S.
on N. face. O.B.T. 40" Fir, bears N.20°W., 18 lks. reblazed
and marked in the bark 1/2 S. 36 C.S.B.T. Other O.B.T. only
stump remains.. New B.T.
Cedar 24" dia. bears S.45°E., 68 lks. blazed and
scribed 1/2 S. 31 C.S.B.T.

SEE CORNER NO. 72

7

CORNER TO SECTIONS 13, 14, 23 and 24.
Renewed from stumps, 20" Oak stump N.17°W., 54 lks.;
Stump of 30" Oak S.47°W., 96 lks. and stump hole 20" Oak
S.82°E., 45 lks. Marked new bearing trees
Fir 10" dia. N.1°W., 4.0 ft. marked S. 14 T.28S.R.8 C.S.B.T.
Fir 15" dia. N.85°E., 17.0 ft. marked S.13 T.28S.R.8 C.S.B.T.
Fir 18" dia. S.72 1/2°E., 8.0 ft. marked S.24 T.28S.R.8 C.S.B.T.
Fir 8" dia. S.30°W., 22.5 ft. marked S.23 T.28S.R.8 C.S.B.T.

SEE CORNER NO. 61

8

SE Cor. Cl. 41
Renew corner from decayed remains of original tree.
Set a fir post and two rocks for corner, from which
A fir 30" in dia., bears N 43 1/4° W 135 lks.

15

9

CS 16 208 15
37 pas 25