

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

32 inch Hemlock N.45 $\frac{1}{2}$ °W., 20.5 feet scribed S.8, T.28S., R.8W., CS BT.
12 inch Hemlock N.16 $\frac{1}{2}$ °E., 6.6 feet scribed S.9, T.28S., R.8W., CS BT.

Oct. 1, 1957

#80
Cont.

$\frac{1}{4}$ Section corner to Section 24 & 25.

Found-Brass cap set by Mench, 1924 Survey, marked US GLO Survey, 1924

$\frac{1}{4}$ S 24
S 25

I find 10" W. Oak bears S.36°E., 11.6 ft. I open & find scribe marks. This BT probably scribed in 1924.

Also find the original 18" now 36" W. O. BT. N.52°E. Record 60.1 ft.

I find to be 56.6 ft. I open & find original scribe mark "S".

Note: No record can be found of Mench's Survey of Sec. 25, T.28S., R.8W.

See letter dated Oct. 1, 1957 from B.L.M., Leonard Berlin.

New Bearing Trees: 12" W.O. bears S.7°E., 9.5 ft. scribed $\frac{1}{4}$ S 25 CS BT.

14" W.O. bears N.67°W.40.7 ft. scribed $\frac{1}{4}$ S 24 CS BT.

Oct. 16, 1957

81

NOT IN SERVICE DUE TO
OF CORNER BACK OF T28/7

$\frac{1}{4}$ Section corner to Sections 26 & 25.

Found-Brass Cap at corner marked US GLO 1924 $\frac{1}{4}$ S26/S25. Neither

original BT. can be found at this time, but I find clump of

Laurel at record distance & bearing for S.E. BT & I find remains

of Oak Stump record distance & bearing for S.W. BT.

BTs. set 1924: 21" R.Fir bears N.82°E., 56.2 ft. shows good face.

I do not open.

10" R.Fir bears N.68°W., 26.5 ft. I open, find scribe

marks " $\frac{1}{4}$ S 26".

New BTs: 21" R.Fir bears N.82°E., 56.2 ft. Bark scribed $\frac{1}{4}$ S25 CS BT.

15" R.Fir bears N.80°W., 55.7 ft. scribed $\frac{1}{4}$ S 26 CS BT.

Oct. 16, 1957

82

James W. Byron, Deputy County Surveyor
M. Godfrey
S. Blom
Oct. 16-18, 1957
C. S. File No. 49/12

Section Corner Common to Sections 23, 24, 26, & 25.

S23 | S24

Found-Brass Cap at corner marked US GLO Survey 1924 S26 | S25 T.28S., R8W.

and one original BT only 18" now 30" B.Oak N.74°W., 27.7 ft.

On chip from old face find scribing "W S", All other original

BTs. gone.

BTs. set 1924: 18" dead R.Fir. I open scribed "W S 26 BT" bears

S.45°W.

26" R.Fir shows good blaze. I do not open.

Bears S.54°E., 14.3 ft.

20" R.Fir shows good blaze. I do not open.

Bears N.51°W., 28.5 ft.

New BTs.: 10" W. Fir bears S.38°W. 36.8 ft. scribed S26 T28S R8W CS BT.

14" W. Fir bears S.34 $\frac{1}{2}$ °E. 22.9 ft. scribed S25 T28S R8W CS BT.

8" W. Fir bears N.78°E. 31.2 ft. scribed S24 T28S R8W CS BT.

20" R. Fir bears N.51°W. 28.5 ft. scribed S23 T28S R8W CS BT.

Oct. 16, 1957

83

Section Corner common to Sections 26, 25, 35, & 36.

Found-US GLO Brass Cap at Corner. I can find No Trace of any of the original BTs.

BTs. scribed 1924: 14" Cedar bears S.31°E., 10.6 ft. shows blaze.

I do not open.

14" R. Fir stump bears N.77 $\frac{1}{2}$ °E., 19.0. I open &

find good scribing "W S25 BT".

18" R. Fir bears S.82°W., 31.3 ft. shows blaze.

I do not open.

The N.W. BT. is down.

New BTs.: 12" R. Fir bears N.12°W., 20.3 ft. scribed S26 T28S R8W CS BT.

12" R. Fir bears S.87°E., 60.6 ft. scribed S36 T28S R8W CS BT.

18" R. Fir bears S.82°W., 31.3 ft. rescribed S35 T28S R8W CS BT.

No trees near in N. E. Quad.

Oct. 18, 1957

84

FD 309p
2/18/6
3/1/61: Dolan, R.L.
M100-24