

Douglas County Surveyor's Record of
Government Corners Renewed

T 28 T. S. R 8 R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 9181

177

Section corner for Secs. 7, 8, 17 and 18
Found - 1972 BLM disk on I.P. firmly set, protruding 4" above ground and properly marked.
16" D.B.H. D. fir bears N.37°E., 35.1 ft. (Rec. 1972, A fir 15" bears N.37°E., 54 lks. slope dist. to cap) Has healed single blaze, no scribing visible.
8" fir, now a 9" D.B.H. D. fir, bears S.62°E., 27.7 ft. Tree has healed single blaze, no scribing visible.
18" fir now a 20" D.B.H. D. fir bears S.17°W., 25.7 ft. Tree has healed single blaze, no scribing visible.
An 18" Fir now a 20" D.B.H. D. Fir, bears N.40°W., 9.9 ft. Tree has healed single blaze, no scribing visible.
Trees are all properly tagged except as noted in new accessories.
New Accessory: Tag on NE BT altered; distance changed to 35.1 ft. to indicate horizontal distance between cap and center of BT root crown.
Added initials DCSO to tag.
Monument lies down steep south slope approx. 250 ft. horz. dist. from BLM Road 28-8-20.

8/9/84

178

1/4 Corner for Sections 16 and 17.
Found - 1975 BLM 3 1/4" disk attached to a 2 1/4" dia I.P. protruding 6" from the ground. Cap properly marked.
Original BTs searched for, no evidence found.
1975 survey, 13" W. fir D.B.H. (Rec. 8" hemlock) bears N.55°E., 32.7 ft. (Rec. N.37°E., 32.7 ft.) Has well healed single blaze, no scribing visible.
A D. fir 21" D.B.H. (Rec. 17" Fir) bears S.82°W., 35.3 ft. (Rec. S.63 1/2°W., 36.3 ft.) Has well healed single blaze, no scribing visible.

Note: BLM notes indicate compass bearings did not include magnetic declination.
New Accessories:

- Bearing tree tags altered to indicate new bearings and distances as noted above in "found accessories".
- 5" W. fir D.B.H. bears N.85 1/2°E., 33.9 ft. scribed X BT on a double blaze.
- 4" W. fir D.B.H. bears S.09°W., 15.7 ft. scribed X BT on a double blaze.

Located on a steep north east slope approx. 75 ft. NE of a sharp curve in the Coos Bay Wagon Rd. and approx. 30 ft. lower than rd surface.

8/13/84

179

1/4 Corner for Sections 5 and 8.
Found - Properly marked, 1970 Doug. Co. Surveyors Office brass cap set on a 1 3/8" I.P. protruding 10" above ground. Ren. #149
Set in crumbled mound of stone. No evidence of steel tube with alum. cap from Ren. #92 and #149 is found.
16" fir now a 24" dia 24" high D. Fir stump covered with Gal. metal cap, shows evidence of a healed blaze, bears S.21°E., 6.7 ft.
16" fir now 22" dia., 18" high D. fir stump covered with a galv. metal cap, shows evidence of a healed blaze, bears N.30°E., 17.4 ft.
No orig. evidence or evidence from 1936 referencing out is found.
Set - We reestablish 2 ft. diam. mound of stone around base of B. cap.
New BTs - 23" D. fir double blazed and scribed "1/4 S8 CS BT" bears S.28°E., 52.5 ft.
19" D. fir double blazed and scribed "1/4 S5 CS BT" bears N.76°E., 87.8 ft.

8/10/84

180

1/4 Corner for Sections 11 and 14.
Found - 1970 County brass cap, properly mkd. on a I.P. protruding 8" above ground. Ren. #142
A 1 1/4" dia. axle shaft that is 1" square on top, protrudes 2" above ground. Ren. #39 Axle shaft touches south side of I.P.
A 10" now a 17" dia. forked madrone with a well healed single blaze on south fork, bears N.53°E., 24.5 ft. (Rec. 23.6 ft. is to center of south fork) Ren. #25
A 14" now 28" D. fir with a well healed single blaze bears S.15°E. 50.3 ft. (Rec. 49.6 ft. is to face). Ren. #25
New BT - A 12" madrone double blazed and scribed "1/4 S11 CS BT" bears N.28°W., 41.7 ft.

8/29/84

Douglas County Surveyors Office
Randall W. Smith and Stephen J. Flause
August, 1984
C.S. 62/21

FD
BRASS CAP
2 BTs 84
BENTZ 7/93
M 112-80

FDOK
R. Dolan
12/94
M 121-53