

Douglas County Surveyor's Record of  
Government Corners Renewed

T 29 T.S. R 1 R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 97401

143

Section corner for Secs. 31 and 32; and Secs. 5 & 6 of T.30-1  
 Found - 1970 brass cap, properly mkd. on a 2" I.P. firmly set, projecting 8" above 2 ft. mound of stone. See Renewals 1, 97, 112.  
 Original stone set alongside with no marks visible. 1 1/4" iron bolt, 27" long lays alongside.  
 Orig., roothole, N.88°E., 36.3 ft. with 30" madrone log alongside with a rotted blaze. (Rec. 32.9 ft.)  
 Orig., a roothole, S.38°E., 32.9 ft. with 22" W. fir log alongside with a rooted blaze.  
 Orig., 34" D. fir, stump, N.61°W., 25.6 ft. (Rec. 25.1 ft.) with healed double blaze.  
 1960 BT, 16" W. fir, S.11°W., 18.9 ft. with healed double blaze.  
 1960 BT, 10" B. oak, N.85°W., 9.6 ft. with healed blaze  
 1973 BT, 10" D. fir, N.12 1/2°E., 45.8 ft. with healed double blaze.  
 New BT - 5" D. fir, S.56°E., 31.0 ft. scribed "T30S R1W S5 CSBT" on a single blaze.  
 Note - Corner is about 100 ft. north of small creek and about 350 ft. south of USFS Road #2810.

FD. B.C. 9/93  
PESKE, M117-62

6/9/83

144

1/4 Corner for Sec. 32; and Sec. 5 of T.30-1  
 Found - 2" I.P. firmly set, projecting 6" above ground with a 2 1/2" brass rock tablet laying on top, properly mkd. (welds broke off.) Ren. #143. Original stone set alongside I.P. with no marks visible.  
 Orig., roothole, S.34°E., 25.7 ft. (Rec. S.34°W.) with 30" D. fir log alongside with healed blaze.  
 Orig., roothole, N.57°W., 10.6 ft. with a 30" D. fir stump alongside with healed blaze.  
 1970 BT, a 8" D. fir, N.70 1/4°E., 36.3 ft. with scribe marks visible on single blaze.  
 1970 BT, a 9" W. fir, S.64°W., 14.9 ft. with healed double blaze.  
 No new monument or accessories. I cemented rock tablet to iron post.

6/20/83

145

Center 1/4 corner for Section 31  
 Found - 2" iron post, firmly set, projecting 6" above a 2 ft. mound of stone with brass cap properly mkd. Ren. #111  
 A 12" npw 14" I. Cedar, S.32°E., 16.8 ft. with scribe marks "C 1/4 S31 BT" and a 1 1/2" d brass washer stamped "RS 430" visible on partially healed double blaze.  
 A 16" D. fir stump, N.81°W., 50.0 ft. with scribe marks "1/4 S31 BT" and a 1 1/2" d brass washer stamped "RS 430" on partially healed double blaze.  
 New BT - A 6" D. fir, N.18°E., 35.5 ft. scribed "C 1/4 S31 CS BT" on a single blaze.

6/7/83

146

CW 1/16 S31  
 Found - 2" I.P. firmly set, projecting 12" above ground with bras cap properly mkd. Shaner survey, M49-43  
 18" D. fir stump, N.28°E., 50.7 ft. with scribe marks "CW 1/16 S31 BT" and a 1 1/2" d. brass washer stamped "RS 430" visible on partially healed double blaze.  
 8" W. fir snag S.76°W., 14.6 ft. with scribe marks "CW 1/16 S31 BT" visible on partially healed double blaze.  
 Set - I added a 2 ft. diam., mound of stone. Iron post now projects 6".  
 New BTs- 14" W. fir, S.28 1/2°W., 19.6 ft. scribed "CW 1/16 S31 CS BT" on a single blaze.  
 13" W. fir, N.33°W., 30.4 ft. scribed "CW S31 1/16 CS BT" on a single blaze.  
 Note - Corner is at NE corner of standing timber and at SE corner of USFS clear cut #29-1W-31-3 approx. 350 ft. East of USFS Rd.#2810.

6/8/83

147

CE 1/16 Section 31.  
 Found- 2" I.P. firmly set projecting 6" above ground with brass cap properly mkd. Shaner survey, M49-43

Jim Landrum, United States Forest Service  
Deputy, Doug. County Surveyors Office  
Witness: Leonard Herzstein  
June 1983  
C.S. 62/10