

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 5 R. W. W. M.

✓ N.W. EXTERIOR "L" CORNER OF CLAIM NO. 44. 11
13
Corner was set in from one old bearing tree. I saw letters on tree and have testimony of Ed Weaver as to identity of tree. New corner is $\frac{3}{4}$ " x 48" Gal. Iron Pipe from which
A White Oak 5" dia. bears S.75°00'W., 52 $\frac{1}{2}$ lks. cen. of tree
A White Oak 12" dia. bears S.69°00'E., 42.3 lks. cen. of tree. *2/73 - COR. FOUND - D.E.G. - M 47-63*

✓ $\frac{1}{4}$ CORNER OF SOUTH BOUNDARY OF SECTION 31. #207 12
I renew this corner from one old B.T. as follows
 $\frac{1}{2}$ " x 48" Galvanized Iron Pipe from which
A White Oak 20" dia. bears N.40°30'E., 96 lks.
A White Oak 16" dia. bears S.72°30'E., 50 $\frac{1}{2}$ lks. *SEE CS 54/108 FOR NOTES*

✓ N.W. CORNER OF CLAIM NO. 44. 18
11
I renew this corner from one old bearing tree. Old scribe marks plainly seen by all. New corner is $\frac{1}{2}$ " x 36" Gal. Iron Pipe, from which
A Black Oak 30" dia. bears S.24°00'E., 104.8 lks.
A Black Oak 18" dia. bears N.13°15'W., 30.0 lks.

✓ $\frac{1}{4}$ CORNER ON SOUTH BOUNDARY OF SECTION 32. 14
I renew this corner on a true line as recorded in the John Remick Weaver Survey. Said corner is a $\frac{3}{4}$ " x 30" Gal. Iron Pipe set 16" under the ground and is 1192.4 from $\frac{1}{2}$ " iron pipe set on river bank on township line. *SEE NOTES C.S. 54/108*

✓ SECTION CORNER COMMON TO SECTIONS 4, 5, 32, and 33. 15
I renew this corner from one old bearing tree. Identified this tree from an old scar and from testimony of the Weaver brothers who remember seeing old letter on tree. *133*
corner is $\frac{3}{4}$ " x 24" Iron Pipe set 14" under the ground and from which
A White Oak 6" dia. bears S.43°30'E., 327.5 lks
A White Oak 6" dia. bears N.56°00'E., 434.9 lks.
An old B.T. bears S.62°00'E., 310.0 lks.

✓ $\frac{1}{4}$ CORNER BETWEEN SECTIONS 23 and 24. 16
Renew from old Government corner. Set in 1" x 40" Galvanized Iron Pipe from which old Government B.T.s were remarked. *Fd. B.C. by G. GRUBB Dec. '81 RM 3-52*

✓ $\frac{1}{4}$ CORNER ON EAST SIDE OF SECTION 24. 17
Renew from Government B.T. Set in a 2" Vise Screw and a Rifle Barrel, from which
A 30" White Oak bears S.75°W., 1.80 chs. *TO SIMIL. - C.I.P.E. BARREL NOT B. WIRE M 96-66*

✓ CORNER BETWEEN SECTIONS 9, 10, 15 and 16. 18
Re-established from which
A 12" Fir bears N.62°55'E., 59 lks. *SEE ALSO #9*

✓ $\frac{1}{4}$ POST OF SECTIONS 8 and 17. 19
Reestablished from which
A Pine 24" dia. bears N.54°W., 63 lks.
A Cedar 13" dia. bears S.85 $\frac{1}{2}$ °W., 67 lks. *140*

✓ SECTION BETWEEN 8 and 9. 20
 $\frac{1}{4}$ Post is pitch pine stake 4" x 3 $\frac{1}{2}$ ft. from which. *Coc #141*
A White Oak 8" dia. bears S.69°W., 9 lks.

✓ CORNER OF SECTIONS 4, 5, 8 and 9. 76 21
Reestablished from which
A Fir 30" dia. bears N. 8 $\frac{1}{2}$ °E., 65 lks.
A Fir 18" dia. bears N.77 $\frac{1}{2}$ °W., 37 lks.
A Fir 20" dia. bears S.26 $\frac{1}{2}$ °E., 6 lks.
A Fir 24" dia. bears S.24°W., 56 lks.

Per done
renewed
4/93 FB 42 15 28

M-35

M. E. Germond Co. Sur.
Ed. Weaver
Oles Weaver
Hank Weaver
Joe Weaver
F. C. Freer
John Dicks
Harry Strong
Chris Christesen

Mar. 1-8, 1917
May 4-9, 1917
Sept. 13, 1917

F. C. Freer D.C. S.
Geo. Frank
H. Yarrdrip
Oct. 1918

Frank Cain Dep. Co. Sur.
Jan. 1920

Recorded by F. C. Freer Co. Sur.

RE-RENEWED SEE CORNER NO. #207 12

RE-RENEWED SEE CORNER NO. 133

RE-RENEWED SEE CORNER NO. 86

RE-RENEWED SEE CORNER NO. 140

RE-RENEWED SEE CORNER NO. 20

RE-RENEWED SEE CORNER NO. 76 21