

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 29

T. S. R 5

R. W. W. M.

FORE-CHAPMAN CO., EUGENE, ORE. 97501

Doug. Co.  
Surveyors Office  
Randall Smith  
Stephen J. Flause  
Terrie Franssen  
May 13, 1991  
C.S. 64/15

1/4 Corner for Sections 31 and 32

231

Found - A 2 1/2" dia. 1979 DCSO brass cap on a 1" O.D. iron pipe protrudes 4" above ground. Ren. #199  
A stone which top measures 10" x 6" protrudes 4" above ground "1/4" is marked on south side bears North 6" from BC/IP.  
A 1" I.D. iron pipe is found along southedge of BC/IP protruding 4" above ground. M 1 - 35  
18" now 38" dia B Oak with a fully healed single blaze, bears S 20°E., 15.2 ft. (Rec. S.15°E., 15.2 ft.) Orig. BT. Orig. NW BT now gone.  
8" now 12" dia. W. Oak with a fully double blaze, bears N.59°W., 57.5 ft. (agrees w/rec.) Ren. No. 131  
28" now 30" dia. B.Oak with an unhealed double blaze, scribing visible "1/4S31CS BT" bears S.31°W., 54.1 ft. (agrees w/rec.)  
New BT - 8" dia. W. Oak, double blazed and scribed "1/4 S31 CS BT" bears N.38°W., 58.8 ft.

5/13/91

Section Corner for secs. 11, 12, 13 and 14

232

Set - Brass Cap.  
BTs - 8" Fir bears N.20°W., 36.2 ft. scribed "T29S R5W S11 BT" on a double face.  
12" Fir bears N.22°E., 54.7 ft. scribed "T29S R5W S12 BT" on a double face.  
12" Fir bears S.88°E., 101.2 ft. scribed "T29S R5W S13 BT" on a double face.  
16" Oak bears S.54°W., 176.1 ft. scribed "T29S R5W S14 BT" on a double face.

4/80

Cor. Secs. 3 & 4; 33 & 34 T28-5

233

Found - 1961 County Surveyor BCIP (Ren. #108)  
16" Fir, N.40°W., 41.1', stump  
16" Fir, N.38°E., 6.7', rotten stump  
16" Fir, N.8°E., 57.3', down  
18" Fir, S.29°E., 20.0', stump  
12" Fir, S.78°W., 39.2', healed  
Scribed -  
28" Cedar, S.86°E., 181.8' "S 34 BT"  
6" Cedar, N.14°W., 106.5' "S 33 BT"  
12" Madrone, North 133.8' "S 33 BT"

1/4 Cor. Secs. 3 & 4

234

Found - 1961 County Surveyor BCIP & 3/4" IP ( Ren. #117)  
21" Cedar, N.21°E., 143.0', stump  
22" Fir, S.64°W., 40.0', stump  
Found no evidence of Markham's BTs  
NOTE: THIS MONUMENT BEARS N.86°40'32"E., 15.71' FROM THE POSITION CALCULATED FOR THIS CORNER.

Cor. Secs. 4, 5, 8, & 9

235

Found - 1" Iron pipe (Ren. #210)  
36" Laurel, N.33 3/4°W., 106.9', healed  
18" Fir, N.77°W., 24.4', stump  
30" Fir, N.8 1/2°E., 42.9', stump  
20" Fir, S.26 1/2°E., 4.0', stump  
16" Maple, S.79 1/2°E., 110.8, healed  
24" Fir, S.24°W., 37.0, ' stump  
Scribed -  
14" Cedar, N.88°E., 14.5', "S 4 BT"  
12" Cedar S.31°W., 4.0', "S 8 BT"

Mark Smalley, L.S. #2354  
For: Roseburg Forest Products Co.  
July/Sept. 1993 M 119-2