

Douglas County Surveyor's Record of
Government Corners Renewed

T 29 T. S. R 7 R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 97501

Gary L. Langlitz
L. E. Monrean
K. Cheney
S. Flause
Doug. Co. Surveyors Off.
Nov. 8, 1977
C.S. 59/42

West Exterior "L" Corner for DLC #46
Found - 2" I.P. firmly set and extending 5" above ground level. (I.P. possibly set by Boyer in 1943, C.S. 31-15).
We find no trace of the orig. bearing trees.
A 3 forked D. Fir stump approx. 50" overall with good scar bears S.87°E., 121.0 ft. (Rec. N.89°E., per Ren. #69 and N.86 1/2°E., per Ren. #146)
A 21" now 26" P. Pine alive and well healed, located on the North edge of a gravelled driveway and at the corner of fences running northerly and westerly, bears N.31°E., 89.4 ft. Ren. #146
New BT - A 12" P. Pine scribed "WNW DLC 46 CS BT" on a double blaze, bears N.53°W., 14.9 ft.

RE-RENEWED CORNER NO. #277

257

11/8/77

R.B. Kimberling
P.L. Earle
April 5, 1978
Doug. Co. Surveyors
Office
C.S. 59/46

Section Corner for Secs. 35 and 36; and 1 and 2 of T30-7.
Found - A 3/4" I.P. 12" above ground, bears S.58°W., 2.0 ft. from corner, with a 3" x 3" squared post at the West side. Ren. #82
An OBT, a 24" Madrone (laurel) bears S.68°E., 27.7 ft. with an opened blaze and visible scribing "S-T30S R7"
A 18" now 24" Madrone (laurel) bears S.83 1/2°W., 35.7 ft. (Rec. S.86°W., 34.0 ft.) with visible scribing "T30S R7" in a double partly healed blaze.
A 30" now 31" Madrone bears N.21°W., 35.0 ft. with visible scribing "3-29" in a double partly healed blaze.
A 15" now 18" Madrone bears N.39°E., 34.0 ft. (Rec. 36.0 ft.) with visible scribing "3-29-R7-BT" in a double partly healed blaze.
A 35" now 39" Madrone bears S.20 1/2°E., (Rec. S.24°E.) 45.0 ft. with visible scribing "S1 T30S R7WM" in a double partly healed blaze.

258

Note: Scrbing is cut horizontal in all blazes.

Set - A 1" x 36" I.P. with brass cap set 6" above ground and marked:
"Douglas County Surveyor" R T 29 S
1978 7 S 35 | S 36
W S 2 | S 1
T 30 S

No new accessories. Corner is at the NW corner of old growth timber.

4/5/78

William Ruppert
For: David Stine
October 1978
M 73 - 73

1/4 Corner for Sec. 3; and Sec. 34 of T.28-7
Found - Boyer's 1/4 Corner, mound of 4 or 5 rocks, one being approx. 4" x 8" x 10" and the remains of a cedar post. Ren. #92
Oak near E-W fence with good scar, N.41°15'W., 386.5 ft.
53" B. Oak with visible "B.T." N.60°30'E., 257.7 ft.
W. Oak with good scar, S.78°10'E., 293.9 ft.
Set - 3/4" Rod at Boyer's Corner.

259

10/78

South 1/4 Corner for Section 14 only.
Found - A 1924 GLO brass cap properly marked protruding 8 ins. above ground.
An 8" D. Fir now 16" bears N.60°E., 44.9 ft. with well healed blaze. 1924 resurvey.
The NW BT is gone.
A 12" R. Fir, now 15" bears N.75°W., 20.6 ft. with well healed double blaze. Ren. #122
An unrecorded 12" Cedar bears S.68°W., 14.6 ft. marked with 9 in. "X" and 9 in. long, blaze on North and South side of tree.
CONDITION REPORT ONLY. NO MONUMENT OR NEW ACCESSORIES SET.

260

2/14/79

North 1/4 Corner for Sect. 23 only.
Found - A 1924 GLO brass cap properly marked, protruding 23" above ground in a mound of stone. per 1924 survey.
A 14" D. Fir, now 22" bears S.11°E., 27.7 ft. with well healed double blaze.
A 6" B. Oak now 8", (rec. White oak), bears S.34°W., 33.6 ft. with well healed blaze. 1924 resurvey.
An unrecorded 10" D. Fir bears N.65°W., 11.0 ft. healed over blazes on south, west and east sides.
CONDITION REPORT ONLY. NO MONUMENT OR NEW ACCESSORIES SET.

261

2/15/79

Karen Reed, Doug. Co. Surveyors Office
Frank C. Silagy
Feb. 14, 15, 1979
C.S. 60/24

FND OK
4/91 M 113-6

FND OK
4/91 M 113-6

1-77