

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 8 R. W. W. M.

18

SECTION CORNER BETWEEN SECTIONS 17 and 18, continued
and X 10" under ground.

New B.T.s.
A 14" Fir S.32°25'E., 470 lks. scribed $\frac{1}{4}$ S.17 C.S.B.T.
A 40" Fir N.56°24'W., 1022 lks. scribed $\frac{1}{4}$ S.18 C.S.B.T.

SECTION CORNER BETWEEN 17, 18, 19 and 20.

Set by double proportionate distances from $\frac{1}{4}$ Section corners N., E., and W. and Section corner S. Set a Sandstone 4" x 6" x 20" 12" underground for corner 10' West from creek bank chiseled X on top and 5 notches on E. face, 1 notch on W. face, 3 Notches on N. face, 3 notches on S. face. Marked.

A 20" Ash N.18°33'W., 1112 lks. Scribed T.29S., R.8W. S.18 C.S.B.T.
A 14" Fir S.52°6'E., 935 lks. Scribed T.29 S. R.8W., S.20 C.S.B.T.

No other tree within reasonable distance in proper quadrants. Peak of Signal Tree lookout house on Kenyon Mtn. is S.61°22'W.
Look out Tree on Kenyon Mt. is S.61°25'W.
Group of high trees on top of Ketchum Mt. is S.33°3'W.

SECTION CORNER BETWEEN SECTIONS 19 and 20.

Set by single proportional measurement along the west line of Section 20.

Set Sandstone 4" x 6" x 14" chiseled X on top and $\frac{1}{4}$ on East face 14" under ground for corner.

A 14" Fir S.18°45'W., 913 lks. Scribed $\frac{1}{4}$ S.19 C.S.B.T.
A 16" Fir S.1°1'E., 865 lks. Scribed $\frac{1}{4}$ S.20 C.S.B.T.

CENTER OF SECTION 20.

Set at intersection of lines connecting opposite $\frac{1}{4}$ Section corner of Section 20. Set a pipe 1 $\frac{1}{2}$ " x 24" driven flush with the ground.

A Yewwood tree bears S.0°72'E., 506 lks. scribed C. S.20 C.S.B.T.

Old Yew wood post used as center of Section bears N.53°37'W., 48.6 lks.

FD. PIPE, No
BT's - 12/04
E. 2206M
M 98-18
9/4/06-DSHO
CS 63/9

1/16 SECTION CORNER BETWEEN THE CENTER OF SECTION 20 AND THE E. $\frac{1}{4}$ SECTION CORNER.

Set a 1 $\frac{1}{2}$ " x 24" Iron Pipe driven flush with the ground for corner. B.T.

An 18" Fir N.53°30'W., 31 lks. scribed C.E. 1/16 S.20 C.S.B.T. (Note on account of Road construction June 9, 1932; I marked a 12" W. Fir S.6 $\frac{1}{2}$ °W., 31.5 ft. F. C. Frear Co. Roadmaster.)

CORNER OF SECTION 1 and 12.

Standard Government Corner. Marked T.29 S., S.1 and S.12 from which

A 10" Fir S.75°W., 9.6 ft.
A 8" Fir N.12°W., 196 ft.

SECTION CORNER BETWEEN 28, 29, 32 and 33.

Set from old original B.T.s. Set a 4" x 4" x 36" Fir Stake 18" in ground.

Fir 60" dia. N.57°W., 51 ft.)
Laurel 12" dia. N. E., Laying down.) Old original B.T.
Fir 12" dia. S.43°W., 35 $\frac{1}{2}$ ft.
Cedar 30" dia. S.5°E., 33 ft.
Fir 8" dia. N.35°30'E., 22.8 ft.

CORNER BETWEEN SECTIONS 2 and 11.

Set a 3" x 3" Fir post and the following new trees set from original B.T.s

A 30" Black Oak N.3°E., 111.0 ft.
A 14" White Oak S.19 $\frac{1}{2}$ °W., 129.0 ft. --133' on 14° slope msmt. Original B.T. dead.

Ben B. Irving Deputy County Surveyor
Jan. 4, 1928.

Vol. 3 P. 280
M 1-63
Witnesses
W. S. Crear, C. McCann, Wm. M. Porter

Eppstein Co. S. Mar. 6, 1931
Wit. B.A. Isane H.L. Eppstein C.S.
Giles N. E. Richardson
Ben Bennet H. Z. Ireland
June 2, 1931

Boyer
Wit. R. Heister
Oct. 22, 1935

CS 14/70

RE-NEWED CORNER NO. #104

RE-NEWED CORNER NO. 105

RE-NEWED CORNER NO. #111

SEE CORNER NO. 99+8 23

SEE CORNER NO. 50 24

19

20

21

21A

22

23

24