

Douglas County Surveyor's Record of
Government Corners Renewed

T. 29 1/2 S. T.S. R. 7 W. R.W.W.M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Byron
& Crew
June 21, 1962
C. S. File
No. 49/139

1/4 Corner to 1/4 S31 T29 1/2 S R7W
S 6 T30 S.R7W
Found - Brass Cap set in 1924 & BT's as follows:
1 1/4" Chinquapin N. 5° E. 87.8 ft. (windfall)
20" Fir S. 21° W. 21.8 ft. (stump) Both show good scars.
Set - 1 1/4" x 36" S. 52° E. 32.6 ft. scribed 1/4 S6 CS BT.
7" Chinquapin N. 34° W. 11.3 ft. scribed 1/4 S31 CS BT.

RE-RENEWED, SEE CORNER NO. #23

18

SEPT 69

Russell B. Bass
For: Longview
Fibre Co.
Dec. 20, 1976
M 62 - 53

Center 1/4 Corner for Sec. 32.
Found - Stake set by Grant & Evans 1953, not found.
Set - 1 1/4" x 36" Stainless steel pipe.
BT - 18" Fir, S. 54° W., 10.34 ft. with screw nail, lead washer, yellow tag.

19

1/4 Corner for Secs. 32 and 33.
Stake not found.
Set - 1 1/4" x 36" Stainless steel pipe by direct measurement.

20

3/11

Howard Johnstone
For: Roseburg
Lumber Co.
July 30, 1980
M 84-80
C.S. 58/214

1/4 Corner for Section 34 only, T.29 1/2-7 (See GLO Vol. 39 Pg. 15813)
Found - 1924 GLO Brass cap and iron pipe marked "AM 1976"
1976 Cadastral Brass cap and iron pipe bears N. 5° 52' 33" W., 5.23 ft.
Set - 5/8" x 40" IR and alum. cap 8.69ft South of 1924 BCIP.
New BT's - 36" Pine, N. 66° E., 19.0 ft.
66" Madrone S. 66° W., 35.0 ft.

12/20/76
20A

ADDITIONS: JANUARY 22, 1981 - - - - -
Scribed new bearing tree for North 1/4 Corner, Section 34, T.29 1/2 S
R. 7 W because new road construction will eliminate O.B.T. 66" Madrone
S. 66° W., 35.0 ft.
Found - 1924 GLO BCIP marked "AM 1976"
Our 5/8" x 40" IR & Alum. cap 8.69 ft. South of BC and on true
line.
36" Pine, N. 66° E., 19.0 ft.
66" Madrone, S. 66° W., 35.0 ft.
Scribed New BT -
11" D. Fir, S. 56° E., 60.2 ft. from Al. cap. (S. 48° E., 64.6 ft.
from G.L.O. brass cap.)

1/22/81

Howard Johnstone
Roseburg Lumber Co.
January 22, 1981
C.S. 58/229

Section corner for Secs. 32 and 33; and Secs. 4 & 5 of T.30-7
Found - PK nail hole in sandstone scribed "CS "+"
18" cedar, N. 71° E., 8.3 ft. (N. 54° E., 9.9 ft.) down - scribe
visible.
21" fir, N. 65° E., 21.7 ft. healed. Ren. #9
36" madrone, S. 15° E., 21.1 ft. Rotted face.
20" pine, S. 36° W., 29.7 ft. healed
17" pine, N. 20° W., 53.5 ft. healed.
Set - 2" brass tablet in concrete grout at PK nail location. Tablet
marked with "LS 498".

21

Howard Johnstone
For: Roseburg
Lumber Co.
June 29, 1984
M 97 - 14

1/4 Corner for Sec. 33; and Sec. 4 of T.30-7
Found - Rock 8" x 6" x 4" exposed, marked "1/4".
24" madrone, N. 51° W., 42.2 ft. rotted face.
9" fir, S. 35° E., 8.0 ft. healed. Ren. #13
19" madrone, S. 19° E., 43.6 ft. healed.
10" madrone, N. 17° E., 16.4 ft. scribe visible.
Set - 5/8" x 48" iron rod and alum. cap along side rock. Cap marked
with "LS 498".

22