

Douglas County Surveyor's Record of  
Government Corners Renewed

T 30 T. S. R 1 R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 2181

213

C O N T - - - -

(1/4 Cor. Secs. 6 and 5)

Found - From 1905 survey, A white fir, 18" now an 18" diam. rotted fir stump bears N.80°W., 15.8 ft. from 1905 corner tree. Has a single blaze with scribing 1/4 S6 BT visible.

No evidence of other 1905 BT is found.

From Ren. #31 two trees are found; bearings and distances are checked from the brass cap monument:

An 11" W. Fir now a 15" DBH white fir bears S.84°E., 45.4 ft. (Rec. S.89°E., 46.1 ft.) Tree has partially healed double blaze with the scribing S5 CS visible.

An 8" white fir now a 12" DBH white fir bears S.56°E., 32.6 ft. (Rec. S.61°E., 32.6 ft.) Tree has partially healed double blaze with some illegible scribing visible.

Variation of bearing and distance from record in the preceeding two bearing trees probably resulted from an improperly declinated compass and an improperly reduced slope distance.

A 6" D. fir now a 6" DBH d. ifr bears S.32°W., 22.4 ft. (Rec. S.32°W., 21.9 ft.) Tree has double blaze with scribing 1/4 S6 BT visible. Ren. #194

Monument location is accepted. The following markings are added to the brass cap monument.

"W.C" The arrow points south to the corner tree.



All accessories are tagged with new DCS0 bearing tree tags.

2/26/81

1/4 Corner for Sections 29 and 30

Found - 1967 County brass cap, properly marked, on 1" I.P. firmly set, projecting 12" above ground. Ren. #30

Orig. 16" D. fir snag, N.10°E., 7.3 ft. with scribe 4" vis. on previously opened blaze and rescribed by Powell in 1967 with scribe 1/4 S29 CS BT" visible on partly healed double blaze.

A roothole, S.84°W., 14.4 ft. with 28" D. fir stump alongside with no marks visible. Ren. #30

I ADD 2 ft. diam. mound of stone with brass cap projecting 4" above.

New BT's- 8" I. cedar, S.46°E., 17.0 ft. scribed "1/4 S29 CS BT" on double blaze.

5" I. Cedar, S.56°W., 21.5 ft. scribed "1/4 S30 CS BT" on double blaze.

4/21/81

Section corner for Secs. 30 and 31; and Secs. 25 & 36 of T.30-2.

Found - 1968 County brass cap, properly mkd. on 1" I.P. firmly set, projecting 4" above ground. Ren. #58

Orig. BT, a roothole, S.45°E., 5.3 ft. with D. fir stump 36" diam. alongside with bark blaze vis. on underside.

18" yew snag, N.37°E., 61.0 ft. with scribe marks "T30S R1W S30 CS BT" vis. on partly healed blaze. Ren. #58

13" Yew, S.50°E., 49.0 ft. with scribe marks "T30S R1W S31 CS BT" vis. on partly healed blaze. Ren. #58

16" Hemlock N.4°W., 47.1 ft. (Rec. W. Fir, 47.5 ft.) with healed blaze. Ren. #58

New BT's- 4" D. fir, N.42 1/4°E., 45.8 ft. mkd. "T30S R1W S30 CS BT" on double blaze.

6" D. fir, S.34 3/4°W., 79.9 ft. mkd. "T30S R1W S36 CS BT" on double blaze.

4/14/81

1/4 Corner for Sections 14 and 15

Found - From Ren. #176, A 1978 brass cap on a 2" I.P. protrudes 3" from a rough pile of stone, properly marked; (RLS 866)

From Ren. #151, a 2 1/2" County brass cap on a 1" I.P. leans north & protrudes 7" from ground.

A stone measuring 14"x11"x6" rests on the north side of county brass cap.

County brass cap bears S.01°E., 14.3 ft. distant from Ruppert B.C. set in Ren. #176. Orig. corner and accessories have been lost since before 1920, no evidence is found. A survey by R.L.S. Ruppert in 1978 indicates the corner location as established in Ren. #3 and perpetuated in Ren. #151 is incorrect. Bearing trees for this position are now referenced to 1978 corner and therefor recorded in this renewal as "new" accessories.

216

Stephen Flause  
Deputy, Doug. Co.  
Surveyors Office  
Terrie Plouff  
Karen Mosely  
Feb. 26, 1981  
C.S. 61/19

Leonard Herzstein  
U.S.F.S., Deputy,  
Doug. Co. Surveyors  
Office  
Witnesses: Tom  
Welford; Jim  
Lardrum  
April, 1981  
C.S. 61/19

Stephen Flause  
Deputy, Doug. Co.  
Surveyors Office  
Karen Mosley  
Terrie Plouff  
April 28, 1981  
C.S. 61/19