

Douglas County Surveyor's Record of
Government Corners Renewed

T 30 T. S. R 1 R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 91891

216

C O N T. - - - -

(1/4 Cor. 14 and 15)

Found - A 19" D. Fir now a 21" DBH D. fir bears N.86 1/2°W., 28.0 ft. scribed "1/4 S15 BT" on a partially healed double blaze. Ren.176
A 10" madrone now an 11" DBH madrone bears N.28°E., 17.0 ft. scribed "1/4 S14 BT on an unhealed double blaze. Ren. #176

1978 1/4 corner as set by Ruppert is accepted as found.

Set - As recorded in "monum ents found", position of brass cap from Ren. #151 is referenced out, the cap is removed and replaced by a 5/8" x 30" I.R. with an alum. cap mkd. "Douglas County Surveyor".

Stone on north side of brass cap from Ren.#151 is not disturb

Following accessories have only bearing and distances to the 1978 corner recorded. All blazes and scribing face 1978 corner reasonably well except where noted:

A yellow pine, 42" now a rotted 60" diam. 48" tall pine stump bears S.74°E., 111.9 ft. distant & has the scribing 1/4 S BT visible on an opened blaze. Ren. #3

A 30" cedar, now a fallen 30" DBH cedar bears S.87°W., 141.1 ft. & has a possible burned blaze facing corner. Ren. #3

A 5" D. fir now a 5" DBH D fir bears S.33°E., 24.3 ft. & ahs a partially healed single blaze with the scribing CS BT visible.

A 6" D. fir now a 7" DBH D. fir bears S. 28 1/2°W., 9.1 ft. & is scribed 1/4 S15 CS BT on a partially healed single blaze facing south 36° east. Ren. #151

All listed new accessories are tagged with DCSO bearing tree tags marked with bearing and distances as here recorded.

4/28/81

217

1/4 Corner to Section 7 only, west side.

Found - Original 30" now 36" D. fir corner tree with no scribe marks visible on previously opened blaze on west side and a healed blaze on east side.

Orig. 22" P. pine snag, N.7°E., 23.8 ft. with healed blaze.

Orig. 12" B. Oak, S.85°E., 20.5 ft. with healed blaze.

A reference monument, a 1 1/4" I.P. firmly set, projecting 6" above ground with brass cap, bears East, 1.7 ft. Ren. #36

Note - The 1/4 corner of section 12 only, T.30S., R.2W, which is a brass cap, bears South, 33.0 ft.

New Accessories:

I add marks "RM" above the date to the brass cap.

A 9" D. fir, N.50°E., 74.0 ft. scribed "1/4 S7 CS BT" on a single blaze.

6/16/83

218

1/4 corner for Section 5; and sec. 32 of T.29-1

Found - 2" I.P. firmly set, projecting 6" above ground with a 2 1/2" brass rock tablet laying on top, properly mkd., (welds broke off) Ren. #127. Original stone set alongside I.P. with no marks visible.

Orig., roothole, S.34°E., 25.7 ft. (Rec. S.34°W.) with 30" D. fir log alongside with healed blaze.

Orig., roothole, N.57°W., 10.6 ft. with a 30" D. fir stump alongside with healed blaze.

1970 BT, a 8" D. fir, N.70 1/4°E., 36.3 ft. with scribe marks visible on single blaze. Ren. #127

1970 BT, a 9" W. fir, S.64°W., 14.9 ft. with healed double blaze.

No new monument or accessories. I cemented rock tablet to iron post.

6/20/83

219

Section corner for Secs. 5 and 6; and Secs. 31 & 32 of T.29-1

Found - 1970 brass cap, properly mkd., on a 2" I.P. firmly set, projecting 8" above 2 ft. mound of stone. See Renewals 6, 125, 132

Original stone set alongside with no marks visible. 1 1/4" iron bolt, 27" long lays alongside.

Orig., roothole, N.88°E., 36.3 ft. with 30" madrone log alongside with a rotted blaze. (Rec. 32.9 ft.)

Orig., a roothole, S.38°E., 32.9 ft. with 22" W. fir log alongside with a rotted blaze.

Orig., 34" D. fir, stump, N.61°W., 25.6 ft. (Rec. 25.1 ft.) with healed double blaze.

Fd.B.C. 9/93
RESUE M117-62

Stephen J. Flause
Deputy, Doug. Co.
Surveyors Office
Karen Mosley;
Terrie Plouff
April 28, 1981
C.S. 61/19

Jim Landrum, United States Forest Service
Deputy, Doug. County Surveyors Office
Witness: Leonard Herzstein
June, 1983
C.S. 62/10