

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 30

T. S. R 1

R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

219

C O N T - -

Jim Landrum, U.S.F.S.
Deputy, Doug. Co.
Surveyors Office
Witness: L. Herzstein
June 9, 1983
C.S. 62/10

1960 BT, 16" W. fir, S.11°W., 18.9 ft. with healed double blaze.
1960 BT, 10" B. oak, N.85°W., 9.6 ft. with healed blaze.
1973 BT, 10" D. fir, N.12 1/2°E., 45.8 ft. with healed double
blaze.
New BT - 5" D. fir, S.56°E., 31.0 ft. scribed "T30S RLW S5 CS BT" on a
single blaze.
Note: Corner is about 100 ft. north of small creek and about 350 ft.
south of USFS Road #2810.

6/9/83

220

Section corner for Secs. 27, 28, 34 and 33.

Found - 1 1/2" O.D. iron pipe with brass cap attached, firmly set, pro-
jecting 12" above a 3 ft. diam. mound of stone. I.P. is
leaning slightly northerly and brass cap is rotated 45° clock-
wise. I use point where the I.P. projects from the mound of
stone as the corner point. Ren. #19

Orig. BT, a 13" D. fir, S.87°E., (Rec. S.82°E.), 29.7 ft. with
scribe marks "S3" visible on previously opened blaze.

Orig. BT, a 32" D. fir stump, N.32°W., 15.2 ft. with no marks
visible.

BTs marked by Tracy in 1967:

Found - A 12" D. fir, N.74°E., 19.4 ft. with healed double blaze.

A 14" I. Cedar, S.72°E., 31.3 ft. (Rec. 31.5 ft.) with partially
healed double blaze.

A 10" D. fir snag, S.19°W., 28.4 ft. with scribe marks "T30S
RLW S33 CS BT" visible on partially healed double blaze.

A 36" D. fir, N.72°W., 17.4 ft. (Rec. 18.0 ft.) with healed blaze.

New BT - A 13" madrone, S.55°W., 26.6 ft. scribed "T30S RLW S33" on
upper bark blaze and "BT" on foot blaze with a brass washer
stamped "LS 1181" nailed to face of lower blaze.

Note - Steel fence post set 3.7 ft. south with USFS signs #54-2 & #54-4
attached. Corner is 40 ft. NW of new USFS road now under
construction and 300 ft. + from its junction with USFS Rd. #31.

221

1/4 Corner for Sections 26 and 35

Found - 20" x 14" x 14" corner stone loose and on top of ground, marked
"1/4" on north side and near record position (N.60°W., 20.5')
from 1922 16" red fir. Ren. #48

Found 1968 County surveyor split pipe monument delivered to office
1922 16" red fir, now 21" scribed "1/4 S35 CS BT" in a single
blaze bears S.60°E., 20.5 ft. meas. from 1922 face. Portion
of orig. scribing "5B" still visible. Tree is from 1922
Mensch resurvey.

Possible orig. 48" fir, present size indeterminable, now a 3 ft.
tall stump bears S.82°W., 6.1 ft. (Rec. S.88°W., 5.9 ft.)
Record distance probably taken to bark. We find the record
bearing 6° too far right. Mensch, in 1922, found an orig. 8"
fir N.60°E., 13.2 ft. from the corner (rec. N.70°E., 19.8 ft.)
i.e. record bearing 10° too far right. No sign of blaze or
scribing.

24" cedar, now a fallen 20" stob 8 ft. tall scribed "1/4 S26
CSBT" in double blaze. Root hole bears N.46°E., 20.6 ft.

Original 8" fir not found. (Rec. N.60°E., 13.2 ft.)

Corner position was established using record position from 1922 16" red
fir (N.60°W., 20.5 ft.). We reset 1968 monument and set corner stone on
the north side of the monument. We add the words "Reset 1984" to brass cap.
Accessories:

Set boat spike stamped "BO 1" thru BT tag in orig. 48" stump
(not in center) bears S.82°W., 7.2 ft.

9" D. fir bears N.8°W., 78.5 ft. and is scribed "1/4 S26 CS BT"
in double blaze.

8" yew bears S.80°E., 33.5 ft. and is bark scribed "1/4 S35 CS BT"

10" yew bears S.9°W., 41.4 ft. and is scribed "1/4 S35 CSBT" in
double blaze.

12/7/84

FD OK
6/9/83 CS 63/78
FD OK 9/92
B SHANER RA 3-76

Maurice E. Farr
L.S. #1181
For: U.S. Forest
Service
Leonard Herzstein
Randy Lopez
Sept. 18, 1984
C.S. 62/15

Douglas County Surveyors Office
L.E. Monrean, Deputy
J.R. Lundeen
S.J. Flause
C.S. 62/21