

Douglas County Surveyor's Record of  
Government Corners Renewed

T 30 T. S. R 2 R. W. W. M.

MOORE-CHAPMAN CO., EUGENE, ORE. 21881

245

C O N T. - - -

Book  
349-Long  
M120-69  
7/94

Jim Landrum, U.S.F.S.  
Leonard Herzstein  
March 2, 1982  
C.S. 61/32

22" P. Pine bears N.5°W., 94.1 ft. part healed blaze with frag. scribe marks visible. Ren. #158  
14" D. fir, bears N.2°E., 103.0 ft. healed face, now snag. Ren#158  
16" D. fir bears S.81°E., 74.4 ft. healed face. Ren. #158  
10" D. fir bears N.89°E., 132.5 ft. partly healed double blaze. Scribes visible "T30S R2W S26""BT". Brass washer with stamp "536" nailed to lower face. BT tag marked by Baughman 2/78. BT not of record. This BT scarred by recent road building.  
New BT - 20" Ponderosa pine bears S.88°W., 108.6 ft. scribed "T30S R2W S34 CS" BT" on dbl. blaze.  
Painted 6" red bank and painted blazes on all BTs and added 54-4 attention signs to BTs. Corner now located - 150 ft. south of new road.

3/2/82

246

Jim Landrum, U.S.F.S.  
Deputy, Doug. Co.  
Surveyors Office  
Witness: L. Herzstein  
June 16, 1983  
C.S. 62/10

1/4 Corner for Section 7 only of T.30-1  
Found - Original 30" now 36" D. fir corner tree with no scribe marks visible on previously opened blaze on west side and a healed blaze o east side.  
Orig. 22" P. pine snag, N.7°E., 23.8 ft. with healed blaze.  
Orig. 12" B. oak, S.85°E., 20.5 ft. with healed blaze.  
A reference monument, a 1 1/4" I.P. firmly set, projecting 6" above ground with brass cap, bears East, 1.7 ft. Ren. #97.  
Note - The 1/4 corner of section 12 only, T.30S., R.2W., which is a brass cap, bears South, 33.0 ft.  
New Accessories:  
I add marks "RM" above the date to the brass cap.  
A 9" D. fir, N.50°E., 74.0 ft. scribed "1/4 S7 CS BT" on a single blaze.

6/16/83

247

Jim Landrum, U.S.F.S.  
Deputy, Doug. Co.  
Surveyors Office  
Witness: L. Herzstein  
June 21, 1983  
C.S. 62/10

Section corner for Secs. 11 and 12 only. (southwest cor. of 12)  
Found - 1" iron pipe, firmly set, projecting 22" above the ground. set by Markham in 1959. Ren. #36  
Original corner stone 6" x 4" x 8" on top of the ground, alongside iron pipe, with no marks visible. I used iron pipe as corner point, as it is the only solid point in the ground.  
Orig. BT, a roothole, N.41°E., 27.7 ft. with 20" madrone log. alongside with decayed blaze.  
1959 BT, a 12" D. fir stump, S.4°W., 19.2 ft. with healed blaze.  
1959 BT, a 11" D. fir stump, S.80°W., 8.0 ft. with healed blaze.  
1959 BT, a 14" madrone snag, N.52°W., 39.0 ft. with scribe marks "S11 R W" visible on previously opened blaze.  
1959 BT, a 12" D. fir stump, N.5°W., 33.3 ft. with healed blaze.  
Section corner to sections 13 and 14 only, bears S.87 1/2° W., 119.0 ft.  
Set - I remove 1" x 40" Iron pipe and in its place I set a 2" iron post 30" long, 19" to bedrock and built a 2 ft. diam., mound of stone to within 6" of brass cap; cap marked "Douglas County Surveyor 1983 T30S R2W S11 S12 "  
S13  
Iron pipe and original stone are buried alongside.  
New BTs - 7" D. fir, N.73°E., 35.6 ft. scribed "T30S R2W S12 CS BT" on a single blaze.  
9" D. fir, N.43°W., 41.7 ft. scribed "T30S R2W S11 CS BT" on a single blaze.  
Note - Steel fence post with USFS signs #54-2 and 54-4 attached bears East, 1.1 ft. causing local attraction.

6/21/83

248

Jim Landrum, U.S.F.S.  
Deputy, Doug. Co. Surv. Office  
L. Herzstein, Witness  
June 21, 1983 C.S. 62/10

Section corner for Sections 13 and 14 only.  
Found - Orig. corner stone 5" x 8" projecting 4" above ground firmly set with "+" on top.  
1" iron rod with piece of iron welded on northerly side, firmly set, projecting 10" above the ground, set by Markham bears N.60°W., 0.3 ft. from the "+". Ren. #37  
I used "+" on orig. stone as corner point as it doesn't appear to have been removed by Markham.  
Found - Remains of orig. BT, a madrone rootcrown, size indeterminate, bears S.76 1/2°E., 10.5 ft.  
1959 BT, a 14" madrone snag, N.11°E., 10.8 ft. with scribe marks "S11 BT" visible on partially healed double blaze.