

Douglas County Surveyor's Record of  
Government Corners Renewed

T 30 T. S. R 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

248

C O N T -

Jim Landrum, U.S.F.S. Deputy, Doug. Co. Surveyors Office  
Witness: Leonard Herzstein  
June 21, 1983  
C.S. 62/10

1959 BT, a 12" D. fir, N.33°E., 9.3 ft. with healed double  
1959 BT, a 36" D. fir stump, S.24°E., 21.0 ft. with scribe marks  
"S13" visible on partially healed upper blaze and bark scribes  
"BT" visible on lower bark blaze.  
1959 BT a 12" madrone snag, S.72°W., 64.0 ft. with healed blaze.  
Section corner to sections 11 and 12 only, bears N.87 1/2°E., 119.0 ft.  
Set - I remove 5" x 8" x 14" original corner stone and in its place  
I SET a 2" iron post, 30" long, set 28" in the ground with  
brass cap marked "Douglas County Surveyor T30S R2W S11 1983"  
1" x 37" iron rod was buried inside iron post S14 S13  
and the orig. corner stone was buried alongside.  
New BTs - 12" D. fir, S.10°E., 28.8 ft. scribed "T30S R2W S13 CS BT"  
on a single blaze. Base of blaze is 2 ft. above ground.  
8" D. fir, S.15 1/2°W., 30.8 ft. scribed "T30S R2W S14 CS BT"  
on a single blaze.  
Note - Steel fence post set with U.S.F.S. signs #54-2 and 54-4 attached  
bears South 1.8 ft. causing the local attraction. Scribe  
marks by Markham are marked starting from bottom to top.  
6/21/83

249

L.E. Monrean, Deputy  
Douglas Co. Surveyors  
Office  
Witness: J.M. Powell  
July 21, 1983  
C.S. 62/9

East 1/4 corner for Section 20 only.  
Found - A 1" iron pipe with attached 1970 County Surveyor brass cap,  
protruding from mound of stone approx. 18". Ren. #178  
Original 72" fir, now 76" diam. with well healed blaze bears  
N.62°W., 46.3 ft. (Rec. 47.5 ft.)  
A 6" D. fir, now 10" with well healed double blaze bears N.14°W.,  
51.1 ft. Ren. #178  
No new monument set. Mound stone around found monument.  
New BT - A 7" hemlock double blazed and scribed "1/4 S20 CS BT" bears  
N.40°W. 27.4 ft.  
Note - Corner is approx. 33 ft. south of creek course east.  
7/21/83

250

Douglas County Surveyors Off.  
Larry E. Monrean, Deputy  
R.W. Smith and S.J. Flause  
August 13, 1984  
C.S. 62/21

1/4 Corner for Sections 8 and 9.  
Found - Firmly set and 8" below the surface, the iron pipe with  
properly mkd. County brass cap. Ren. #164  
The original stone, measures approx. 11" x 8 1/2" x 5". The center  
of the stone bears N.44°E., 0.5 ft. from the brass cap mon.  
The faint mark "1/4" was located on the bottom of the stone  
as found. (Photo in C.S. file).  
Orig. 12" maple, double trunk with northerly trunk split & dead  
No scribing found, bears S.53 1/2°W., 5.9 ft. to center of  
root crown. Ren. #240 calls 4.2 ft. dist. which checks well to  
center of trunk at apparent ground level (slide activity has  
covered lower portion of the trunk). (Orig. Fir BT not found.)  
Ren. #164 BTs as recorded in Ren. #240:  
Found - 8" fir now an 11" fir stump with tin roof, partially healed blaze  
bears N.55°E., 54.0 ft.  
12" W. fir dead and down.  
14" now 20" D. fir with scribing "1/4 S8 BT" visible in  
partially healed blaze bears S.78 1/2°W., 63.3 ft. (Rec.  
S.76°W.). Ren. #240.  
16" now 22" D. fir with scribing "1/4 S9 BT" visible in partially  
healed blaze bears S.40°E., 48.9 ft. Ren. #240.  
No new monument set. Area excavated to expose brass cap.  
New BT's- 17" D. fir double blazed and scribed "1/4 S8 CS BT" bears  
S.36 1/2°W., 14.5 ft.  
15" maple double blazed and scribed "1/4 S8 CS BT" bears  
N.69°W., 30.7 ft. (Lower blaze bears N.67°W.)  
8/13/84

251

Howard Johnstone  
For: Roseburg Lbr.  
Sept. 20, 1984  
C.S. 58/296

Section corner for Secs. 16 and 21 only.  
Found - 1968 County brass cap and iron pipe and stone. Ren. #167  
36" Fir, N.25°E., 25.4 ft. snag and rotten.  
32" fir, S.72°E., 12.5 ft. snag and rotten.  
New BTs - White Fir, 12" N.31°E., 37.8 ft. scribed with sec. and BT.  
Cedar, 6" S.24°E., 38.0 ft. scribed with sec. and BT.

RE-RENEWED, SEE CORNER NO. #276  
RE-RENEWED, SEE CORNER NO. #275