

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 3 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21861

Bruce A. Shaner
For National
Plywood Inc.
March, 1960
Map File M 17-51

North $\frac{1}{4}$ Corner Section 2.
Set $\frac{3}{8}$ " x 30" Brass Rod:
Marked: Fir 6" diam. S. $61\frac{3}{4}^{\circ}$ E. 25.4 feet, $\frac{1}{4}$ " S2 BT
Fir 10" " S. 3° E. 20.0 feet, $\frac{1}{4}$ " S2 BT

177

S. E. Corner Section 32., as det. by O.B.T.
22" Dead Fir Snag N. 75° E. 8.6 ft. dist. O.B.T. fd. scribe.
Both other BT's. burnt off at ground level.

178

At Corner Point found Stone and Set $\frac{3}{4}$ " x 30" I. P. from which:
20" Cedar N. 7° E. 6.0 ft. S33 R3W B.T.
20" Cedar N. 5° W. 22.0 ft. S32 R3W B.T.
20" Cedar S. 35° W. 34.0 ft. S 5 T31S X B.T.
16" Cedar S. 1° W. 34.7 ft. S 5 T31S R3W B.T.

CORNER NO. 181

$\frac{1}{4}$ Corner Section 32 and 33, as det. by O.B.T's:

20" Fir S. 27° E. 27.1 ft. O.B.T.
16" Fir S. 19° W. 13.9 ft. O.B.T.

179

At Corner Point Set $\frac{3}{4}$ " x 30" I. P. from which:

50" Cedar S. 78° E. 29.5 ft. $\frac{1}{4}$ " S33 B.T.
8" Fir N. 42° W. 10.9 ft. $\frac{1}{4}$ " S32X B.T.
7" Fir N. 40° E. 15.3 ft. $\frac{1}{4}$ " S33 B.T.
12" La. S. 88° E. 32.6 ft. $\frac{1}{4}$ " S33 T30S R3W B.T.

F.D.I.P. 4/80 BLM
ADMIN. SURVEY
SEE GIS FILE

Sec. Corner 28 - 29 - 32 - 33, as det. by O.B.T's:

22" B. O. Snag N. 60° E. 38.4 ft. O.B.T.
26" Fir windfall S. 70° W. 19.8 ft. O.B.T., fd. scribe.
24" Laurel N. 82° W. 30.1 ft., fd. scribe, O.B.T.
16" Cedar, uproot, S. 69° E. 17.8 ft. O.B.T.

FD OK 80
BY RUPPERT
4/86
C.S. 6/26

At Corner Point found Stone & Set $\frac{3}{4}$ " x 30" Iron Pipe from which:

30" La. N. 70° W. 36.0 ft. S29 T30S R3W B.T.
24" Cedar S. 76° E. 27.0 ft. S33 R3W B.T.
5" Fir S. 55° E. 11.8 ft. S28 B.T.
5" Chip. S. 47° W. 9.7 ft. S32 B.T.

$\frac{1}{4}$ Corner Section 29 and 32., as det. by O.B.T's:

20" Fir Stump, logged, N. 70° E. 15.2 ft., O.B.T.

81

At Corner Point Set 2" x 36" Truck Axle with flange up from which:

24" Fir S. 41° E. 122.0 ft. $\frac{1}{4}$ " S32 BT.
14" Fir N. 73° W. 59.0 ft. $\frac{1}{4}$ " S29 BT.

A good rock road loops the corner.

Road bears South 35.0 ft.
Road bears East 41.0 ft.

RE-RENEWED SEE CORNER NO. #219

X S. W. Corner Section 32, as det. by O. B. T's:

32" Fir S. 72° E. 30.0 ft. O.B.T., fd. scribe.
9" Fir Snag N. 28° E. 22.1 ft. O.B.T.

82

At Corner Point Set $\frac{3}{4}$ " x 40" I. P. from which:

30" La. bears N. 88° E. 47.0 ft. dist. mkd. S32 T30S R3W B.T.
9" La. bears N. 58° W. 19.0 dist. mkd. S31 T30S R3W B.T.
12" La. bears S. 17° W. 26.0 ft. dist. mkd. S 6 T31S R3W B.T.

CORNER NO. 186

X S. W. Corner Section 34, as det. by O.B.T's:

40" Fir S. 71° E. 19.8 ft. O.B.T.
20" Fir Snag N. 14° E. 32.6 ft. O.B.T., fd. scribe

83

At Corner Point Set $1\frac{1}{2}$ " x 36" Pipe from which:

30" La. Snag, live, bears S. 34° E. 18.0 ft. dist. mkd. S4 T31S R3W BT.
20" Fir N. 88° W. 11.4 ft. mkd. S33 T30S B.T.
28" Fir S. 84° W. 26.8 ft. mkd. S4 T31S R3W B.T.
15" Fir S. 62° W. 15.8 ft., already scribed.

Corner lies 30 ft. East of Top of Side Ridge.

CORNER NO. 189