

Douglas County Surveyor's Record of  
Government Corners Renewed

T 30

T. S.

R 4

R.W.W.M.

ROSE-CHAPMAN CO., EUGENE, ORE. 21991

272

Section corner for Secs. 10, 11, 15 and 14.

Found - Orig. monuments not found.

Fd. 1963 brass cap properly marked from Ren. #195

Orig. R. Fir, 8" diam. now a snag 22" diam. with well healed double blaze bears S.35°E., 34.6 ft. (orig. dist. 35.6 ft., 1889 records show bearing S.31 1/2°E., 35.6 ft.)

An 1889 BT a 10" Fir now a stump 24" diam. bears N.49°E., 21.0 ft. (rec. 19.8 ft.) Stump has previously opened blaze with scribing visible "R4W" Also reverse scribing "R4W found on pieces of chopped out blaze laying on stump. A ring count shows tree growth 60 to 70 years after blaze and scribing.

A D. Fir 15" now a 16" snag bears N.73 1/2°E., 13.9 ft. (rec. N.75°50'E., 14.8 ft.) Tree bark scribed "S11 3683 BT".

A 20" R. Fir now a 24" snag, bears S.84°W., 16.4 ft. (rec. S88°W 17.5 ft.) Tree has partially healed pitched over blaze. Ren.#195

No new monument set.

New BT's-A 7" Madrone bears S.25°E., 22.1 ft. tree blazed and scribed "T30S R4W S14 CS BT" on double blaze.

A fir 20" diam. bears N.29°E., 35.2 ft. Tree bark scribed "T30S R4W S11" on lower blaze scribed "CS BT"

A Fir 18" bears N.52°W., 78.9 ft. Tree blazed and scribe "T30S R4W S10 CS BT" on double blaze.

Note: Old east west fence bears south 2.6 ft.

4/30/79

Gary L. Langlitz  
L.E. Monrean  
P. Earle  
Doug. Co. Surveyors  
Office  
Witness: Elmer  
Sutton.  
April 30, 1979  
C.S. 6024

Glenn Baughman  
For: Longview Fibre  
July 1979  
M 78 - 30

Center 1/4 Section 6

Set - 5/8" Iron rod

BT's - 8" Madrone bears N.31°E., 28.8 ft. scribed C 1/4 S6 BT double face

6" Madrone bears S.21°E., 18.1 ft. scribed C1/4 S6 BT double face

7/79

1/4 Corner for Secs. 9 and 16

Found - A 1 1/4" Axle protruding .75 ft. above ground set by Eppstein in 1928. Ren. #44

No orig. trees found.

A fir stump approx 30" diam. bears N.63°E., 16.5 ft. Stump badly rotted (Ren. #44 and 69) (Rec. N.71°E.)

A 16" red fir now 18" bears N.30°E., 64.4 ft. with well healed double blaze. Ren. #144

A 46" R. Fir, now 54" bears N.19°W., 278.7 ft. with well healed blaze. Ren. #144 (Rec. 275.4 ft.) 276.4 ft. to face.

Set - No new monument set.

New BT's- A 8" D. fir scribed "1/4 S16 CS BT" in a double blaze bears S.79°E. 97.3 ft.

A 10" broad leaf maple scribed "1/4 S16 CS BT" in a double blaze bears S.22°W., 141.9 ft.

Previous renewals do not state bearings and distances from orig. trees.

8/20/79

Karen Reed  
Doug. County Surveyors  
Office  
Frank Silagy  
Peter Earle  
Aug. 20, 1979  
C.S. 60/34

William Ruppert  
For: Jim L. Jenks  
Sept. 1980  
M 85 - 39

East 1/16 corner Section 21 and Sec. 28

Set - At proportionate distance, set 1" x 28" iron rod and steel post for guard stake

1/2" steel bar dound per C.S. 55/291 bears N.8°13'E., 3.44 feet.

35" Fir, Bears N.84°15'W., 29.8 ft. See Ren. #95

1/4 Corner for Sections 21 and 28.

Found - 1" iron pipe. See Ren. #94

Set - 5 ft. steel post alongside pipe.

Set 5 ft. steel post, S.81°27'E., 14.40 ft.

Found - 18" B. Oak, possible Markham BT, bears N.67°24'W., 108 ft. Did not open. No other trees close by.

-9/80

O V E R

273