

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 7 R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 21681

James W. Byron
M. Godfrey
C. Putnam
April, 1960
C.S. 52/25

Secs. 12 & 13, T30S. R7W. & Sec. 7 & 18, T30S R6W. 27
Found - Orig. 20", now down, 30" Laurel N.89°W. 36.3 ft., shows
good reverse scribing "B" "2".
Orig. 20", now 30" Laurel S.25°W. 49.5 ft. Center rotted. #153
Orig. 7", now 12", down & rotted, Laurel N.79°E. 28.4 ft. FD. 1977
No trace of Orig. SE BT. found. BLM ADMIN.
Set Brass Cap at Corner Mkd: County Surveyor's

S12	S 7	T30S
R7W	S13	S18 R6W

SURVEY SEC
Office, 1960 GIS FILE
New BT's: 14" R. Fir bears N.18°W. scribed S12 T30S R7W CS BT.
12" R. Fir bears N.20°E. 15.5 ft. scribed S 7 T30S R6W CS BT.
8" R. Fir bears S.23°W. 17.8 ft. scribed S13 T30S R7W CS BT.
8" R. Fir bears S.29°E. 26.8 ft. scribed S18 T30S R6W CS BT.

Howard W.
Johnstone
For Roseburg
Lumber
C.S. File No.
51/163

Sec. Cor. to Secs. 18 & 19, T30-7W. & Secs. 13 & 24, T30-8W. 28
Could not locate the Original Corner Stone.
Found - 8" Fir N.72°W. 9.9 ft.
17" Fir N.38°E. 34.3 ft.
Set - 1" x 30" Iron Pipe in Stone Mound.
12" Fir S.69½°E. 53.0 ft.
15" Fir S.37°W. 68.5 ft.

September 15, 1961

James W. Byron
& Crew
April 1962
C.S. File
No. 49/139

Renew Township Corner

S36	S31	T29S
R7W	S 1	S 6 R6W T30S

29
Found - All BT's. as recorded by Markham, 1956. See Cor. No. 21.
We do not find Bolt set at Corner. #125
Set - Brass Cap at Cor. Mkd: County Surveyor's

S36	S31	T29S
R7W	S 1	S 6 R6W T30S

Note - We find Stone N.20°W. 1.5 ft. from corner that may have been
set for corner.

Howard W. Johnstone
For Roseburg Lumber Co.
May 28, 1962
C. S. File No. 51/163

¼ Corner between Sections 13 and 14. 30
Found - 8" Fir N.60°E. 8 lks. (badly burned)
8" Fir S.82°W. 18 lks. (good condition)
Set - 1½" by 24" Iron Pipe
Scribed - 10"D. Fir S.44½°E. 21.6 feet.

¼ Corner between Sections 13 and 24. 31
Found - 60" Laurel N.65°E. 35 lks. (dead) See #11
Set - 1½" by 24" Iron Pipe
Scribed - 18" D. Fir N.18°W. 22.0 ft.
16" D. Fir S.72°W. 25.5 ft.

¼ Corner between Section 19, T30-7W. & Sec. 24, T30-8W. 32
Found - 40" Fir is corner mkd. on west face (good)
36" Fir N.48°E. 68 lks. (down)
14" Fir N.80°W. 36 lks. (burned, no visible scribe)
Set - 1½" by 24" Iron Pipe.
Scribed - 6" Doug. Fir N.68°E. 65.4 ft.
20" D. Fir S. 7°E. 41.0 ft. (no trees in the west to scribe)

O
V
E
R