

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 3 W. R. W. W. M.

KOKS-CHAPMAN CO., EUGENE, ORE. 31881

171

Cl. Corner to Sections 18 and 19, only, T31-2W.

Found - 24", now 30" Fir N. 70° E. 7.3 ft., shows good scar.
24", now 30" Fir S. 31° E. 13.2 ft., shows good scar.
Squared Stake at C. Corner, N. face scribed S18, 3 Notches.

Set - Brass Cap at Sec. Cor. Mkd: County Surveyor's Office, 1966

T 31 S R	
3 S 24	S 18 2
	S 19 W

John M.
Powell &
Crew
Jan. 28, 1966
C. S. File No.
52/63

Both Bearing Trees in good condition.

172

1/4 Corner to Section 30, T31-3W. & Sec. 25, T31-4W.

Found - Iron Pipe at 1/4 Corner, See Ren. #17.
Orig. 40" Fir, S. 50 1/2° E. 47.8 ft., shows good scar,
has been opened for scribing.
20", now 23", Laurel N. 29° 49' W. 21.7 ft., (bearing S.B.N. 32° W.)
(scribe visible "1/4 S CSET".)

Set - Brass Cap alongside I.P. Mkd: County Surveyor's Office, 1966

T31S	
R4W S 25/S 30 R3W	

New BT: 7" Laurel S. 53° E. 4.7 ft. scribed 1/4 S30 CS BT.

173

1/4 Corner to Sec. 7, T31-3W. & Sec. 12, T31-4W.

Found - No trace of Iron Pipe at Corner, See Ren. #90, T31-4W.
6" Fir, Down, S. 84° E. 42.0 ft.
7", now 8", D. Fir S. 75° E. 35.0 ft., shows good scar.
12", now 13", D. Fir N. 29° W. 31.0 ft., BT scribe visible.
Orig. Corner Tree had been opened for scribe "1/4" on W. face.
Orig. 28" D. Fir N. 19° E. 40.3 ft.

Set - Brass Cap at 1/4 Cor. Mkd: County Surveyor's Office, 1966

T31S	
R4W S 12/S 7 R3W	

As noted Road bears North 290.0 ft.

John M. Powell
Frank Jones & Jae Brady
March 1966
C. S. File No. 54/20

1/4 Corner to Sections 27 and 26.

Found - Co. Surv. Crew visited this corner, Feb. 1960 and found it in good condition. See Map M 31 - 28.
Set - 1" I. Pipe from which a: (Set by R.M. Thompson, May 1960)
11" Fir bears S. 33° 20' W. 14.1 ft.
12" Fir bears N. 64° 45' E. 18.4 ft.

May 1960

North 1/16. Corner btwn. Secs. 26 and 27.

Set - 3/4" Iron Pipe from which a:
28" Fir bears S. 0° 45' W. 12.0 ft.
36" Fir bears N. 72 1/2° W. 16.6 ft.

(Corner Set by Robert M. Thompson, May 1960 for Superior Lumber Co.)

May 1960

Robt. M. Thompson
For Superior
Lumber Co.
May 1960
M 31 - 28

176

1/4 Corner to Sections 35 and 36.

Found - No trace of 6" Fir N. 21° E. 14.5 ft.
18" Fir, now 34", S. 81° W. 20.4 ft., opened for scribing. "4".
Set - Brass Cap at 1/4 Cor. Mkd: County Surveyor's Office, 1966

T31S R3W	1/4 S 35/S 36
----------	---------------

New BT's: 20" D. Fir N. 7° W. 75.2 ft. scribed 1/4 S35 CS BT.
Reblazed & Rescribed: 34" D. Fir S. 81° W. 20.4 ft. scribed 1/4 S35 CS BT.
Note - This corner lies in cut unit about 600 ft. East of logging road.

John M. Powell
Frank Jones
April 4, 1966
C. S. File No. 52/63

Sec. Cor. to Sections 25 - 26 - 35 - 36.

Found - 18" Fir, now 15", N. 38 1/2° W. 23.4 ft. scribe visible "T31".
30" Fir, now stump, S. 75° 50' E. 24.0 ft. scribe vis. "S36CS BT."
No trace of 28" Fir N. 59° 20' E. 31.3 ft. (Road)
No trace of 12" Fir S. 2 1/2° W. 10.5 ft.
No trace of Iron Pipe as recorded in Ren. #27.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966

T31S R3W	S 26 S 25
	S 35 S 36

New BT's: 26" D. Fir N. 26° E. 30.0 ft. scribed T31S R3W S25 CS BT.
15" D. Fir S. 68° W. 25.6 ft. scribed T31S R3W S35 CS BT.
Note - This corner lies on edge of old, logging road.

RE-RENEWED CORNER NO. #213 174

RE-RENEWED CORNER NO. #211

RE-RENEWED CORNER NO. #210