

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

86

$\frac{1}{4}$ Corner to Sections 9 and 16.
Found - $1\frac{1}{4}$ " Iron Pipe at Cor., See Ren. #21.
12" W. Fir, now 13", N. 64° W. 41.3 ft., shows good scar.
12" Yew, now 11"?, N. 74° E. 38.5 ft., scribe visible " $\frac{1}{4}$ S9 BT".
Corner Tree Stump scribe visible " $\frac{1}{4}$ S".
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966

	T31S	R5W
$\frac{1}{4}$	$\frac{S}{9}$	
	$\frac{S}{16}$	

All Bearing Trees are in good condition.
Logging Road bears South 25.0 ft.

87

$\frac{1}{4}$ Corner to Sections 10 and 15.
Found - Wooden Stake at $\frac{1}{4}$ Corner, distances to face of trees, Ren. #12.
Orig. 32" Cedar, now 36", S. 45° W. 7.9 ft., bark scribed " $\frac{1}{4}$ S"
28" D. Fir, now 32", S. 16° E. 5.0 ft., pitched over, scribing legible
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966

	T31S	R5W
$\frac{1}{4}$	$\frac{S}{10}$	
	$\frac{S}{15}$	

Reblazed & Rescribed: 36" Cedar S. 45° W. 7.9 ft. scribed $\frac{1}{4}$ S15 CS BT.
New BT: 16" Laurel N. 19° E. 15.5 ft. scribed $\frac{1}{4}$ S10 CS BT.

88

$\frac{1}{4}$ Corner to Sections 9 and 10.
Found - $1\frac{1}{8}$ " Iron Pipe at Corner, See Ren. #35.
8" Fir, broken off, S. 82° W. 40.3 ft., scribe visible.
48" Cedar, Now Stump, S. 53° E. 78.0 ft., scribe visible, S10 T31SR5WBT
New BT's: 6" D. Fir scribed $\frac{1}{4}$ S 9 CS BT, N. 83° W. 21.6 ft.
18" Cedar S. $24\frac{1}{2}^\circ$ E. 92.9 ft. scribed $\frac{1}{4}$ S10 CS BT.

89

$\frac{1}{4}$ Corner to Sections 27 and 26.
Found - 14" D. Fir, now 24" Tree Dead, S. 75° W. 29.7 ft. very faint bark scribe "S". Other marks not legible.
15" Fir N. 70° E. 13.2 ft., No trace.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966

	T31S	R5W
$\frac{1}{4}$	$\frac{S}{27}$	$\frac{S}{26}$

New BT's: 10" D. Fir N. $69\frac{1}{2}^\circ$ W. 5.4 ft. scribed $\frac{1}{4}$ S27 CSBT.
12" Yew N. 32° E. 35.2 ft. scribed $\frac{1}{4}$ S 26 CS BT.
Note - This corner lies south of ridge 90.0 ft.

90

Section Corner to Secs. 17 - 18 - 19 - 20.
Found - 1" Iron Rod at Corner, See Ren. #26.
Orig. 36" D. Fir N. 68° W. 15.2 ft. Opened for scribe, non visible, bark scribe, "BT".
12" W. Fir, now 14", N. 40° W. 6.9 ft., Opened for scribe "31" visible.
7" W. Fir, now 9", S. 72° E. 13.4 ft., good scar.
9" W. Fir, now down, S. 24° W. 29.6 ft., Tree down.
New BT: 14" W. Fir S. 86° W. 37.6 ft. Mkd:
8" W. Fir N. 51° E. 41.4 ft. Mkd:

April 18, 1966

Sec. Corner to Sections 17 - 18 - 19 - 20. (REPEAT - SEE ABOVE)
Found - 1" Iron Rod at Sec. Cor., See Ren. #26.
Orig. 36" D. Fir N. 68° W. 15.2 ft. Opened for scribe, none visible. Bark scribe, "BT".
12" W. Fir, now 14", N. 40° W. 6.9 ft., opened for scribe "31" visible
7" W. Fir, now 9", S. 72° E. 13.4 ft., good scar.
9" W. Fir, now down, S. 24° W. 29.6 ft.
New BT's: 14" W. Fir S. 86° W. 37.6 ft. scribed $\frac{1}{4}$ S19 CS BT.
8" W. Fir N. 51° E. 41.4 ft. scribed $\frac{1}{4}$ S17 CS BT.

John M. Powell
Frank Jones & Joe Brady
May and June 1966
C. S. File No. 54/25

RENEWED, SEE CORNER NO. #116