

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

JAMES W. BYRON, CO. SURVEYOR
FOR B. L. M.
May 12, 1969
C.S. File No. 54/86 M 37-62

John M. Powell & Crew
June, 1967
C.S. File No. 54/31

Sec. Cor to Sec. 3 & 2, T31-6W. and Secs. 34 & 35 T30-6W. #151 129
Corner set from survey at proportionate distance.
Set - Brass Cap at Cor Mkd: County Surveyor's Office 1969
T 30 S R 6 W
S 34 | S 35
S 3 | S 2
T 31 S R 6 W
New BT's: 22" B.Oak S.36°30'E. 70.0 ft. mkd: "T31S R6W S2 CS BT.
7" Cedar N.81°W. 37.6 ft. mkd: "T30S R6W S34 CS BT.
23" D.Fir N.15°W. 10.7 ft. mkd: "T30S R6W S34 CS BT.
14" D.Fir S.25°W. 40.5 ft. mkd: "T31S R6W S 3 CS BT.

1/4 Corner to Sec. 2, T31-6W and Sec. 35, T30-6W. 130
Corner set from survey by portionate measurement,
Set - Brass cap at 1/4 Corner Mkd: County Surveyor Office 1969
T 30 S R 6 W
S 35
S 2
T 31 S R 6 W
New BT's: 16" D.Fir N.82°30'E. 22.6 ft. mkd: "1/4 S35 CS BT.
12" W.Oak S.61° E. 100.1 ft. mkd: "1/4 S 2 CS BT.
Old fence N - S bears west 49.0 ft. (Ren. #144 of T. 30-6) searched for, not found)

Sec. Cor. to Secs. 7 & 18, T31-6 and Secs. 12 & 13, T31-7W. (ANGLE 131
Found - Hyde's Section Corner. - No trace of N.E. or SW. BT. POINT
36", now 41" D.Fir S.22°E. 7.9 ft. Tree has been opened, SEE CADASTRAL NOTES
scribe visible "BT". Ring count of this tree places it at
the correct time to be Hyde's corner.
12", now 28" Cedar, N.27°W. 18.5 ft., center of tree burnt out.
Set - Brass Cap at Cor.Mkd: County Surveyor's Office 1967
R T 31 S R
A.P. 7 S 12 | S 7 6
W S 13 | S 18 W
New BT's: 13" Cedar N.64 1/2°W. 16.1 ft. mkd: T31S R7W S12 CS BT AP.
15" Cedar S.20°W. 29.8 ft. mkd: T31S R7W S13 CS BT AP.
24" D.Fir N.38°E. 23. 4ft. mkd: T31S R6W S 7 CS BT AP.
(NOT COMMON CORNER - ANGLE POINT ONLY - CADASTRAL MAP 6/5/67
SEE COR. FILE T 31 S R 6 W SOUTH)

Section cor. of sections 28-27-33-34. 132
Found-14" D.Fir, now down, N.66°W. 28.4 ft. Tree had been opened,
found 2 pieces of bark, scribing "1" & "R".
No trace of other BT's.

Set - Brass cap at cor. mkd: County Surveyor's Office 1970
T31S R6W
S 27 | S 27
S 33 | S 34
New BT's-40" D.Fir N.8°E. 69.2 ft. Scribed: T31S R6W S27 CS BT.
37" D.Fir N.40°W. 31 ft. Scribed: T31S R6W S28 CS BT.
37" D.Fir S.22 1/2°W. 53.4 ft. Scribed: T31S R6W S33 CS BT.
39" D.Fir S.80°E. 60 ft. Scribed: T31S R6W S34 CS BT.
2/4/70

Section Corner to Sections 9 - 10 - 15 - 16. 133
Found - Orig. 12" Yew, out of the ground, with scribe "3" visible.
1" BLM Iron Pipe that was agreed to be corner by BLM & C.&D.Lumber.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1970
T 31 S R 6 W
(Set B.C. alongside I.P.) S 9 | S 10
S 16 | S 15
New BT's: 48" D.Fir S.11°E. 96.7 ft. scribed "T31S R6W S15 CS BT.
5" Alder N.85°E. 10.5 ft. scribed T31S R6W S10 CS BT.
36" D.Fir S.67°W. 10.0 ft. scribed T31S R6W S16 CS BT.
18" Yew N.14°W. 59.2 ft. scribed T31S R6W S9 CS BT.
Note - Corner lies on west side of creek at record distance.

MAR 71

JAN 78

9/14/70