

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 31      T. S.      R 7      R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 91881

Howard Johnstone  
For: Roseburg  
Resources  
August 14, 1986  
C.S. 63/26

127

Center 1/4 Corner for Section 35  
Found - 1964 Cadastral brass cap, properly marked.  
26" fir, N.34°E., 42.9 ft. now stump, Drove 3/8" square  
X 12" boat spike in center of stump.  
21" fir, S.53°W., 16.5 ft. now stump, drove 3/8" square  
X 12" boat spike in center of stump. Stump is covered  
with light sheet metal, painted white.

**New Accessories:**

28" D. fir stump, drove 3/8" square X 12" boat spike in  
center, N.21°W., 28.3 ft.

Set a 4 ft. light weight fence post along side the brass cap.

**Note:** Corner falls in the middle of clear cut limit. No trees  
suitable for new BTs.

Howard Johnstone  
L.S. #498  
For: Roseburg  
Resources Co.  
May 19, 1989  
C.S. 63/95

1/4 Corner for Sections 26 and 27

Found - 26" D. fir, N.2½°W., 21.0 ft. healed face, good condition.  
Renewal #25.

No evidence of any other BTs of record.

Brass cap and I.P. had beendug out during fire trail construction.

Set - Reset the I.P. and B.C. in their proper location from the re-  
maining D. fir BT. (1964 Cadastral B.C. & I.P.)

New BT - 8" chinquapin, S.10°W., 38.4 ft. scribed "¼ S27 BT".

(No trees available to scribe in Section 26 as it has been recently  
clear cut.)

5/19/89

Douglas County  
Surveyors Office  
Randall Smith  
Stephen J. Flause  
Oct. 26, 1992  
C.S. File 64/32

1/4 Corner for Sections 18 and 19

Found - 2" dia. 1977 brass cap set in concrete on road cut bank. Ren. #102

18" now 18" dia. dead D.Fir with a partially healed single  
blaze, scribing visible "1/4 BT" bears S.81°E., 54.0 ft.  
(Rec. S.81°E., 52.2 ft.) Ren. No. 102

7" now 8" dia., W.Oak with a partially healed rotted single  
blaze, scribing visible "1/4 BT" bears N.59°E., 79.4 ft.  
(Agrees w/record.) Ren. No. 102

New BTs - 17" dia. Madrone double blazed and scribed "1/4 S18 CS BT"  
bears N.89½°E., 66.6 ft.

9" dia. D.Fir double blazed and scribed "1/4 s19 CS BT" bears  
S.59½°W., 81.5 ft.

Corner lies approx. 12 ft. East of road.

10/26/92

1/4 Cor. Secs. 25/36

Found - 1977 County BCIP & 1" IP. Ren # 104

22" Fir, N.59°E., 42.8', Part. healed.

24" Fir, S.40°E., 5.3', high stump.

New BTs - 5" Fir, N.12°E., 18.1', "¼ S BT"

7" Fir, S.70°E., 23.5', "¼ S BT"

8" Pine, S.10°E., 19.2', "¼ S BT"

5" Fir, S.50°W., 23.3', "¼ S BT"

131

1/4 Cor. Secs. 36 & 31 T31-6

Found - 1½" IP & 1966 County BCIP (Not set) (REN # 56)

28" Fir, N.34°W., 15.2', stump.

16" Fir, N.58°E., 14.8', (19-8) Part. healed.

New BTs - 6" Yew, N.44°E., 24.0', "¼ BT"

30" Fir, S.58°E., 23.5', "¼ BT"

28" Fir, S.35°E., 47.6', "¼ BT"

**RECORDED CORNER NO. # 135**

Mark Smalley, L.S. #2354  
For: Kenneth Ford  
July 1994 M 120-43

1/4 Corner Secs. 36; & 1 T32-7

Found - 1½" IP (Ren. #75)

30" Cedar N.25°E., 34.5', healed.

24" Pine, S.24°E., 28.2', Part. healed.

New BTs - 10" Fir, N.19°W., 13.7', "¼ S BT"

6" Fir, N.57°E., 18.6', "¼ S BT"

132