

Douglas County Surveyor's Record of
Government Corners Renewed

31 T. S. 8 R. W. W. M.

KOEC-CHAPMAN CO., EUGENE, ORE. 97196

1
 $\frac{1}{4}$ CORNER FOR SECTIONS 14 & 23
 Both BTs found and are still live trees.
 The 10" Pine (now 22")
 The 22" Pine (now 34")
 Set 3"x3' Fir Stake, marked $\frac{1}{4}$ S 23, $\frac{1}{4}$ S 14, T 31 S, R 8 W.

Section corner to secs. 31 & 32, T 31 S., R 8 W., and secs. 5 & 6, T 32 S., R 8 W.

Original corner could not be found after intensive search so corner set by proportionate measurement.

Set $\frac{1}{2}$ inch iron pipe for corner.

Scribed four trees:

- 5 inch Tan Oak, N.59°30'E., 6.3 feet.
- 12 inch Tan Oak, S.10°00'E., 11.1 feet.
- 6 inch Tan Oak, S.29°00'W., 28.6 feet.
- 6 inch Tan Oak, N.81°30'W., 21.8 feet.

3
 $\frac{1}{4}$ corner between sec. 32, T 31 S., R 8 W., and sec. 5, T 32 S., R 8 W.

Found 2 original B. T.s:

Set $\frac{1}{2}$ inch iron pipe for corner point.

Scribed 1 new B. T.:

- 14 inch Madrone, N.15°00'W., 8.1 feet.

Section corner to secs. 20, 21, 28 & 29.

No trace of the original corner could be found.

Corner reestablished by proportionate measurement.

Set a $1\frac{1}{2}$ inch iron pipe, from which:

- 5 inch Madrone, N.15°15'E., 24.9 feet.
- 5 inch Madrone, S.69°00'E., 8.9 feet.
- 30 inch Fir, S.12°10'W., 24.1 feet.
- 6 inch Madrone, N.40°00'W., 6.5 feet.

5
 $\frac{1}{4}$ corner to section 1, T31 S, R8W., and section 36, T30S, R8W.

Found 2 O. B. T.s:

- 24 inch Pine, S.25°E., 18 lks.- Rotten snag.
- 30 inch Pine, N.60°E., down and rotten.

Set 4 inch x 4 inch x 48 inch D. Fir post.

Blaze and scribe 2 new B. T.s:

- 6 inch W. Fir, N.36°E., 33 lks. mkd. $\frac{1}{4}$ S 36 R. E. 2741 B. T.
- 16 inch D. Fir, S.24W., 27.5 lks. mkd. $\frac{1}{4}$ S 1 R. E. 2741 B. T.

6
 Section corner to secs. 1 & 2, T31S, R8W., and secs. 35 & 36, T30S, R8W.

Point for corner established by proportionate measurement, between $\frac{1}{4}$ corners.

Set a 3 inch x 3 inch x 36 inch D. Fir stake.

Blaze and scribe B. T.s:

- 10 inch Madrone, S.78 $\frac{1}{2}$ °E., 13.2 feet mkd. T31, R8, S-1-R. E. 2741 B.T.
- 3 inch D. Fir, S.72°W., 6.2 feet mkd. "X" - B. T.
- 8 inch Madrone, N.51°E., 17.9 feet mkd. T30, R8W., S-36, R. E. 2741 B.T.
- 7 inch Madrone, N.6°W., 17.2 feet mkd. T30, R8, S-35, R. E. 2741 B. T.

7
 $\frac{1}{4}$ Section Corner between Sections 4 & 9.

From Old Witness Trees:

The 12" Chinquapin which bears N.72°W. 39 links now being a broken off stump and,

The 12" Chinquapin which bears S.22°W. 19 links being a stump hole with the uprooted stump lying near.

Set 4" Hemlock post 4 feet long for the corner and scribed 2 new trees:

- A Fir 16" in diam. N.18°E. 25.8 feet marked $\frac{1}{4}$ T31S, R3W, Sec. 4 2807 BT. This tree has a cruiser mark (Gilbert)
- A Fir 5" in diam. S.56°W. 15 feet marked $\frac{1}{4}$ T31S, R8W. S 9.

Milner L. Larson
 July, 1956
 C. S. File No. 42/167.
 Map file No. M 3 - 3.

Milner L. Larson
 July, 1956
 C. S. File No. 42/168.
 Map file No. M 3 - 4.

Arthur R. Evans
 Work done for Martin Bros. Box Co.
 April 18 & 19, 1956.
 C. S. File No. 42/197.

Richard C. Grant
 D. Powell - W. Oilar
 Bob Carter
 Martin Bros. Box
 Jan. 21, 1958
 C.S. File No. 42/328

Fwd. O.K.
 by STEVEN NEES #811
 Dec. 1981 M 89-65
 AD OK, APR 1995
 1995-0040