

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31

T. S.

R. 9

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Douglas County
Surveyor's Office
Randall W. Smith
Stephen J. Flause
November 1992
C.S. 64/35

1/4 Corner to Sec. 24 in T. 31S R9W, and Sec. 19 in T.31S R8W
Found - 3" dia. 1962 BLM Resurvey brass cap on 2 1/2" outside **179**
dia. I.P. firmly set & protruding 6" above ground.
An orig. 24" now 34" diameter breast high Douglas Fir w/
fully healed dbl. blaze bears N.71°E., 48.2 ft. (Rec.
N.71°E., 47.5 ft.; a face measurement)
Bearing trees from BLM Resurvey renewal:
12" now 19" diameter breast high Douglas Fir w/fully healed
dbl. blaze bears N.18 1/2°E., 7.6 ft. (as per Record)
12" now 17" diameter breast high Douglas Fir w/fully healed
dbl. blaze bears N.86 1/2°W. 40.8 ft. (Rec. N.86 1/2°W., 41.6 ft.,
distance to center of trunk level with cap)
Both trees have a small upper blaze & a large lower blaze.
New BT - 4" diameter breast high Douglas Fir scribed "X BT" on a dbl.
blaze bears S.63°W., 16.8 ft.
Monument is near east edge of random border clear cut & is approx. 100
ft. westerly from BLM forest access road in east 1/2 of Sec. 19, T31S, R8W

180

Corner for Sections 15, 16, 21, 22
Found - 2 1/2" dia. Brass cap on a 1 1/2" O.D. by 36" long iron pipe,
found loose in root wad of tipped out tree. BC/IP has no
position. See renewal # 106.

Accessories Found -

- 72" now 50" dia. 15 ft. high rotted D.Fir snag, no scribing
or blazes visible. Bears N.50°E., 21.8 ft. (agrees with
record) O.B.T.
- 60" now 66" dia. 10 ft. high D.Fir stump with a "W"
cruisers axe mark in bark, no blazes or scribing visible.
Bears S.70°W., 59.4 ft. (agrees with record) O.B.T.
- 60" now 48" dia. 3 ft. high D.Fir stump with illegible
scribing visible. Bears N.40°W., 69.5 ft. (rec. N.40°W.,
66.0 ft. orig. rec.) O.B.T. Distance of 72 ft. from
renewal #106 is a slope measurement.
- Found remains of old stump near rec. bearing and dist. of
orig. 18" W.Fir. (rec. S.45°E., 85.8 ft.) O.B.T.
- 12" now 10" dia. 1 ft. high rotted D.Fir stump, no blazes
or scribing found. Bears S.73°W., 21.7 ft. (rec.S.67°W.,
21.7 ft. renewal #106)
- All other BT's from renewal #106 are tipped out of ground
and positions are not determinable.

Monument set - D.C.S.O. BC/IP is set from positions of original BT's
as determined from accessories found. The mark "reset
1995" are added. BC/IP protrudes 2" above ground.

-Note: S16 and S15 are now marked in correct quadrants.

New Accessories -

- 9" Madrone bark scribed "T31S R9W S16 CS BT"
bears N.20°W., 28.0 ft.
- 13" D.Fir double blazed and scribed "T31S R9W S21 CS BT"
bears S.20 1/2°W., 24.0 ft.
- 18" D.Fir double blazed and scribed "T31S R9W S15 CS BT"
bears N.86 1/2°E., 18.1 ft.
- 19" D.Fir double blazed and scribed "T31S R9W S22 CS BT"
bears S.43 1/2°E., 36.5 ft.

Center 1/4 Cor. Sec. 12

181

Set- 5/8"x30" iron rod 29" in the ground w/2" alum. cap
stamped: T31S R9W C% • S12 2001 PLS 1941
14" D.Fir bears S.1°27'26"E., 20.8 ft. scribed "C%
S12 BT"
16" D.Fir bears N.81°52'41"W., 34.0 ft. scribed "C%
S12 BT"
5/8"x30" iron rod w/plastic cap mkd: "BTS ENG-SURV"
bears S.81°52'41"E., 20.0 ft.
5/8"x30" iron rod w/plastic cap mkd: "BTS ENG-SURV"
bears N.1°27'26"W., 20.0 ft.

See note on next page concerning BTs.

Kris DeGroot
For: Roseburg
Resources

June 2001

M137-13