

Douglas County Surveyor's Record of
Government Corners Renewed

T 32

T. S.

R 2

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

124

1/4 Corner for Section 24; and Sec. 19 of T32-1

CORNER REPORT ONLY

Found - 2 1/2" dia. I.P. firmly set, flush with a 2 ft. mound of stone with a 3" dia. brass cap set by Glenn Baughman in 1976. Ren. #83
A steel fence post bears east, 3.9 ft. with U.S.F.S. signs #54-2 and 54-9 attached, as a guard post.
A 7" cedar, S.02°E., 3.1 ft. with scribe marks "T32S R1W 1/4 S19" visible on partially healed double blaze with a 3/4" brass washer stamped "LS 536" nailed flush to lower blaze.
A 10" D. fir, N.29°W., 18.4 ft. with healed double blaze.
An unrecorded BT by Baughman in 1976" a 12" D. fir, S.51°E., 20.2 ft. with scribe marks "T32S R1W S19 BT" visible on partially healed double blaze with a 3/4" brass washer stamped "LS 536" nailed flush to lower blaze.

7/15/85

1/4 Corner for Sections 20 and 21

125

Found - 2" dia. pipe with brass cap attached marked "1/4 S20 S21 1968 OLS 536", protruding 15" above ground set firmly in a mound of stone. Ren. #37
(Original stone not found, not searched for.)
Original 36" now 43" dia. fir stump with visible scribe "1/4 S20" bears S.23°W., 27.3 ft.
Ren. #37 BT, 9" dia. stump, fir, 2 ft. high with scribe "BT" visible bears S.48°E., 7.3 ft.
(No other BTs found.)

New Accessories:

11" Fir, double blazed and scribed "1/4 S21 CS BT" bears S.34 1/2°E., 5.4 ft.
8" Fir, double blazed and scribed "1/4 S20 CS BT" bears S.56°W., 23.0 ft.
12" Chinquapin, double blazed and scribed "1/4 S20 CS BT" bears N.57°W., 17.3 ft.
Set 8" x 1/2" Boat spike and DCSO bearing tree tag in pitch ring of 60" fir stump. Spike bears N.43°E., 34.3 ft. DCSO tag marked "...Douglas County Surveyor's Office..."

Clear Cut in NE-NW and SE quads.

9/5/85

Section corner for Secs. 5, 6, 7 and 8.

126

Found - Stone measuring 14 x 9 x 7 inches (Record 15x12x8) lying slightly recessed in the ground (not firmly set.) No notches or marks distinguishable.
A fir, 30" now 53" dia. with well healed blaze bears S.8°E., 43.9 ft. (Rec. 46.9 ft. checks when measured along ground slope) We open blaze and find scribing "S 8".
Record 12" now 27" fir with well healed single blaze bears S.24 1/2°W., 27.6 ft. (Rec. 29.7 ft. checks when measured along ground slope.) We open blaze and find fragmentary scribe marks 4 to 5 inches from center of tree.
Set - 1" x 30" iron pipe with brass cap 24" deep at position of found stone. Cap is marked "Douglas County Surveyor T32S R 2 W S6 S5 S7 S8 1985". Stone is placed at SSE edge of brass cap monument.
New BTs- 20" W. fir double blazed and scribed "T32S R2W S6 CS BT" bears N.16°W., 34.5 ft.
21" D. fir double blazed and scribed "T32S R2W S 5 CS BT" bears N.33 1/2°E., 26.0 ft.

Monument lies approx. 200 ft. + South from the intersection of USFS Roads 32 and 3200-260.

9/5/85

GO TO NEXT PAGE

Maurice Farr LS 1181
U.S.F.S.
Leonard Herzstein
Party Chief
Randy Lopez, witness
July 15, 1985
C.S. 62/26

Larry E. Monrean, Deputy, Douglas County
Surveyors Office
Randall Smith and Stephen J. Flause
Witnesses.
September 5, 1985
C.S. 62/29

RE-RENEWED SEE CORNER NO. #133