

Douglas County Surveyor's Record of
Government Corners Renewed

32 T. S. 6 R. W. W. M.

Ben B. Irving J. W. Cole. C. S.
Surv. July 1923
F. Smith N. M. Richardson
R. Irving Witness
Witnesses Rev. Ge. Vol. 1 R.

May, 1922
G. G. Stewart D. C. S.
Mit. Neff Wit. Wilson,
R. Payne Pickett G. Booth
K. Cooper W. Damewood B. Damewood
W. Damewood

Siskiyou Timber
Sur. D. F. Thene
Dec. 11, 1951
"Grants Pass, Oregon"
40-395

COR. BET. SEC'S 32-33 T32 S R 6 W SAME AS #2 21
I renewed this corner from the burned out stump of old Bearing tree N 83° W 353 lks. also hole where other Bearing tree had stood bears N 49° E 170 lks. also fences corner at the place located from trees I set a 1 1/2" x 24" Galv. pipe and erected mound of rock around it. Marked two points of ledge rock for Bearing objects. N 45° W 11.2 ft. and N 21° 30' E 40.8 ft.

CORNER TO SECS 27-28-33-34 T32R 6W. SAME AS #3 22
I renewed this corner by setting a 1 1/2" x 30" steel bar at the point where an old Yew wood post stood all Bearing trees had been cut but stumps remained. SEE CORNER NO. 100

1/4 COR. BET. 33-34 N. 6° 31' E. 108.7 23
Set from O. B. T's. SEE CORNER NO. 50
Set 3/4" iron rod, marked new B. T's. as follows:
24" W Oak, blazed and scribed 1/4 S 34 - C.S.B.T. - set brass disc. ←
18" W. Oak, blazed and scribed 1/4 S 33 - C.S.B.T. - set brass disc. ←
N. 69° 21' W. 44.0

~~SEC. COR. 7 - 18 & 12 & 13 (T 32 S, R 7 W)
Set iron bar from 2 O.B.T. stumps. Others gone
Marked 24" Fir N 16° E 183.2 ft.
30" Fir N 71° E 216.0 ft.
No other trees available~~

~~SEC. COR. 6 - 7 & 1 - 12 (T 32 S, R 7 W)
Set iron pipe from 2 O.B.T.s Others gone
Marked a 30" Pine N 54 1/2° E 26.8 ft. (O.B.T.)
10" B. O. S 30° E 47.4 ft.
20" B. O. N 5° W 95.2 ft.
18" B. O. S 44° W 121.0 ft.~~

~~1/4 COR. BET. 7 - 12 (T 32 S, R 7 W)
Set iron bar from stump of O.B.T.
Marked a 12" Fir N 89° W 218.0 ft.
10" Fir N 56° E 143.0 ft.~~

THESE CORNERS
ARE IN T 32 S,
RGS. 4 & 5 W.
SEE 45/186.

1/4 corner to sections 30 and 31. (Found Sec. corner to 29, 30, 31 and 32 marked with a 3/4" Iron Rod.) 24
I ran west along the section line on 19° 45' var. to a 1/4 corner of section 30 and 31.
Found Madrone bearing tree which was dead and broken off 10 ft. above the ground. Scribe bears N. 32° E 9.2 ft.
Set 1/2" Iron pipe at corner. SEE CORNER NO. 68