

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 32 S. T. S. R. 6 W. R. W. W. M.

71  
Sec. Cor. to Secs. 2 & 1, T32-6W. & Secs. 35 & 36, T31-6W.  
Found - Orig. 14", now 30" Fir N.30°W. 38.9 ft., shows scribe marks  
on partly rotted face.

Orig. 6", now down 12" Fir S.53°E. 33.0 ft., shows scar.

No other Original BT's. found.

Set - 2" Iron Rod at Corner.

New BT's: 12" Hemlock bears N.80°W. 50.0 ft. scribed S35 T1SR6W CS BT.

12" Hemlock bears S.12°E. 3.5 ft. scribed S 1 T32S R6W CS BT.

9" Cedar bears East 43.1 ft. scribed S36 T31S R6W CS BT.

James W. Byron, Dep.  
For: C. & D. Lumber  
April 2, 1963  
C.S. 53/12  
Map M 25 - 10

72  
Fd. by 1/4 Corner to Sections 10 and 15.  
SMITH 4/27/83  
M 94-19  
Set - 5/8" Drill Steel from 2 Original BT's.

Sec. Cor. common to Sections 10 - 11 - 14 - 15.

Set - 5/8" Drill Steel - Set by double prop. See explanatory notes  
in C. S. File No. 51/255.

73  
Fd. by New BT's: 10" Fir S.39°41'W. 2.4 feet.  
SMITH 4/27/83  
M 94-19  
12" Madrone S.19°20'E. 19.5 feet.  
22" Fir N.3°33'E. 41.6 feet.  
6" Sugar Pine N.20°35'W. 46.4 feet.

Lorne V. Swearingen  
For Robert Dollar Co.  
C.S. File 51/255  
Map File M 25 - 48

74  
Sec. Corner to Sections 13 - 14 - 23 - 24.

Found - 1" Iron Pipe - Old Madrona BT. N.55°W. 15.2 ft., down. *Ren #14*

Old BT. S.86°05'W. 39.4 feet.

Scribed - 6" Madrona S.61°20'W. 19.6 feet.

10" Chinq. N.52°07'W. 12.9 feet.

6" Madrona N.30°45'E. 13.7 feet.

George J. Wenderoth, Deputy  
For R. L. Vanduline  
May 23, 1963  
C. S. File No. 53/21

75  
1/4 Corner to Sections 23 and 24.

No sign of old Corner - Set by Prop. Measurement.

Set - 1" I. Pipe for 1/4 Corner.

Scribed - 12" Fir N.11°47'E. 29.4 feet.

16" Cedar S.39°15'W. 38.0 feet.

RE-RENEWED CORNER NO. 153

James W. Byron  
For C. & D. Lumber  
Aug. 1958  
C.S. 49/112

76  
Sec. Cor. to Sections 23 - 24 - 25 - 26.

Found - 2" I. Pipe at Corner & 14" Pine S.25°E. 3.7 ft., bark scribed.

16" B.Oak S.72°W. 14.9 ft., scribed. *Ren #51*

Scribed - 16" Fir N.61°W. 51.0 feet.

14" Fir S.63°30'E. 37.5 feet.

77  
Fd 8/90 M 110-48  
Southeast Corner of Sec. 36, T32-6W. R6W. S36/S31 T32S S 1 T33S R5W

Found - 1 1/4" Axle at Corner & Large Fir Stump S.37°W. 45.5 feet.

New BT's: 8" R.Fir N.3°30'W. 15.4 feet. (scribed by R.E. 3024)

40" R.Fir N. 7°E. 42.0 feet. (3/19/68-revisited cor. & fd. as M 12 - 51

recorded-Call to ck. to W. checks rec.-find 23" Laurel, center rotted, NE BT. Aug. 1958  
(see add'l notes C.S.49/112)

Center of Section 31.

At the legal center of Section 31, we drove a 2" Gal.

I. Pipe within a larger pipe in place & put a cap on the

2" pipe die marked "CENTER SECTION 31 1543", from which: #19

33" R.Fir bears S.77°58'W. 76.3 ft. dist., mkd on bark,

RE-RENEWED CORNER NO. 1543

CEN SEC. 31, B T 1543

James W. Byron  
For C. & D. Lumber  
Aug. 1958  
C.S. 49/112

H. W. Lawrence  
For Forthering  
ham.  
July 1957  
C. S. File  
No. 42/296

79  
FD OK 8/90 M 112-14

Center of Section 31

Found - 2" Iron Pipe with cap Mkd: Center Sec. 31.

(See C. S. File No. 42/296 for map showing center) #18

Stump of BT. S.77°58'W. 76.3 ft., bark scribed.

Took Two New Bearings: RR Rail mkd. RR property line

N.10°50'W. 61.8 feet.

RR Rail marked R.R. Property line N.14°45'E. 114.4 ft.

Both are rails set in ground & extend about 3 ft. above ground.

Geo. J. Wenderoth  
Feb. 1964  
C. S. 49/8