

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 32 T. S. R 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

122

Section Corner for 25 and 36: Secs. 30 and 31 of T.32-7

Found - 2½" dia. 1967 DCSO brass cap on a 1½" O.D. Iron pipe protruding 18" above ground. Ren. No. 56
 Orig. 18" now 20" dia. D.Fir stob with illegible bark scribing, bears S.10°W., 44.8 ft. (Rec. S.10°W., 47.5 ft.)
 8" now 13" dia. D.Fir with a fully healed double blaze, bears S.85½°E., 13.4 ft. (Rec. East, 13.4 ft.)
 8" now 9" dia., D.Fir with a partially healed double blaze scribe marks visible, bears S.78°E., 15.0 ft. (Rec. S.78°E., 16.1 ft.)
 9" now 13" dia. D.Fir with a fully healed double blaze, bears N.34°W., 3.5 ft. (agrees w/rec.)
 10" now 10" dia. Madrone with a partially healed double blaze scribing visible "32S R8W S36 CS BT" bears S.4°W., 24.1 ft. (Rec. S.4°W., 25.2 ft.)
 Set - A mound of stone is added around base of DCSO BC/IP. Brass cap protrudes 3" above 3 ft. x 2 ft. x 15" deep mound of stone.
 No new Accessories.

EO OK 1/6/96 Shaner - M123-17 - 12/10/92
 123

Section corner for 7 and 18 only. (West bdy)

Found - No evidence of original basalt stone or brass cap monument of 1917 resurvey found.
 No evidence of original BTs found.
 1917 BT, A 30" dia., now a fallen and out of position 39" DBH D.Fir with possible healed blaze, the root hole of which bears S.82°E., 37.6 ft. (as per record)
 36" D.Fir now a 42" DBH D.Fir with a double blaze, upper blaze is fully healed, lower blaze is partially healed and shows illegible scribing, bears N.70½°E., 57.3 ft. (as per record)
Renewal No. 37
 Set - Monument is set at position determined from found 1917 resurvey bearing tree root hole and Ren. No. 37 bearing tree (previously described) Monument is a 2 3/8" dia. brass cap marked "Douglas County Surveyors Office T32S

R	S 7	R
9	S 18	8
W		W

1992

BC on a 1½" O.D. 32" I.P. set protruding 4" above ground.
 New BTs - 6" DBH Tan Oak scribed "X BT" on a double blaze bears N.22½°E., 40.6 ft.
 8" DBH D.Fir scribed "T32S R8W S7 CSBT" on a double blaze bears N.39½°E., 68.3 ft.
 5" DBH D.Fir scribed "X BT" on a double blaze. This is a pistol butt Fir of which the base of the vertical portion of the trunk bears S.52°E., 28.7 ft.

This corner lies in bottom of a steep ravine 800 ft. South of a Jeep road and 1,000 ft. West of BLM Road 32-9-14.4

12/13/92

1/4 Corner for sections 29 and 32

124

Found - 2½" dia. brass cap on a 1½" O.D. iron pipe, protruding 12" above ground. Ren. No. 102.
 Found broken stone around base of brass cap with iron pipe, largest stone measures 8"x8"x5". No marks found. (Orig. stone).
 15" now 24" dia. 4½' high double trunked Douglas Fir stump with a partially healed single blaze "1/4 S 32 CS BT" on easterly trunk, root crown bears S 63°E, 13.2' (agrees with rec.) Orig. BT
 14" now 21" dia. 3½' high Douglas Fir stump with a partially healed double blaze "1/4 S 29 CS BT" bears N 57°W, 13.9' (rec. N 54°W, 14.5') orig. BT.
 No bark scribing found on BT's. Marks possibly removed when rescribed in Ren #102.
 New BTs - 4" Douglas Fir double blazed and scribed "X BT" S 6°E, 27.8 ft.
 10" Douglas Fir, double blazed and scribed "¼ S 29 CS BT" bears N 44½°E, 51.9 ft.

4/1/93

Douglas County
 Surveyors Office
 Randall Smith
 Stephen Flause
 Dec. 10, 1992
 C.S. File 64/35

Douglas County
 Surveyors Office
 Stephen Flause
 John Pike
 Dec. 13, 1992
 C.S. File 64/35

Douglas County
 Surveyors Office
 Randall Smith
 Stephen Flause
 4/1/93
 C.S. File 64/41