

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 32 S. T. S. R. 9 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Brandt, Ronald A.  
For: Robert Dollar  
C.S. 55/257

1/4 Corner to Sections 9 and 16. 73  
Found - Brass Cap, set 1917 by G.L.O., See Ren. #19.  
Old 9" Hemlock Stob, N.85°E., 16.0 ft., pushed over.  
14" Hemlock N.34°E. 11.8 ft., now 15.6" DBH.  
16" Hemlock S.53°E. 12.0, now 19.2" DBH to be felled.  
New BT: 22" DBH Hemlock S.37°31'E. 31.27 ft. mkd: 1/4 S 16 PE 6803 BT.  
Note - One BT damaged in logging so replaced with New BT.

6/19/72

JAN 8

3/77  
JAN 78

1/4 Corner for Section 35 only, T.31-9 74  
Found - Orig. 18" x 12" x 6" basalt stone with "1/4" on the north face, now 18" x 11" x 6" with "1/4" on a face, lying at the approx. corner location. The stone was found earlier by a BLM crew somewhere in a slide area below the cor. location and moved to the approx. correct location. The 1917 brass cap appears to have been buried by slide.  
Orig. 36" fir now 42" with good scar.  
11" fir, per Ren. #12, now 11" snag approx. 30 ft. tall with scribed "1/4 S35 CS BT" visible in unhealed blaze.  
Set - At record bearing and distance from both remaining BTs, I set a 1" x 30" iron pipe with brass cap attached, marked "Douglas Co Surveyor T31S 1/4 S35 1982".  
Orig. 36" now 42" fir bears S.60°E., 27.1 ft.  
11" fir now 11" snag bears N.80°W., 78.1 ft.  
Corner is set in a steep bank and orig. stone was placed on east side of new monument.  
New BTs - 10" maple scribed "1/4 S35 CS BT" in double blaze bears N.22°E., 73.5 ft.  
21" fir, scribed "1/4 S CS BT" in single blaze bears S.88°W., 52.8 ft.  
Douglas County Surveyor Office bearing tree tags on all trees.

9/16/82

75

Section Corner for Secs. 7 and 18 only of T.32-8  
Found - No evidence of original basalt stone or brass cap monument of 1917 resurvey found.  
No evidence of original bearing trees found.  
1917 Fir 30" dia. now a fallen and out of position 39" DBH D.Fir with possible healed blaze, the root hole of which bears S.82°E., 37.6 ft. (as per record)  
A 36" D.Fir now a 42" DBH D.Fir with a double blaze, upper blaze is fully healed, lower blaze is partially healed and shows illegible scribing, bears N.70 1/2°E., 57.3 ft. (as per record. Ren. No. 41)  
Set - Monument is set a position determined from found 1917 resurvey bearing tree root hole and Ren. No. 41 bearing tree, previously described. Monument is a 2 3/8" Dia., brass cap on a 1 1/4" O.D. 32" long I.P. set protruding 4" above ground. Cap is marked:  
"Douglas County Surveyors Office" T32S

R	S 7	R
9	S 18	8
W 1992		W

New BTs - 6" DBH Tan Oak scribed "X BT" on a double blaze bears N.22 1/2°E., 40.6 ft. dist.  
8" D.Fir scribed "T32S R8W S7 CS BT" on a double blaze, bears N.39 1/2°E., 68.3 ft. dist.  
5" DBH D.Fir scribed "X BT" on a double blaze. This is a pistol butt Fir of which the base of the vertical portion of the trunk bears S.52°E., 28.7 ft. dist.

This corner lies in bottom of a steep ravine 800 ft. South of a Jeep road and 1,000 ft. West of BLM road 32-9-14.4

12/13/92

Gregory Quibell, Deputy  
Doug. Co. Surveyors  
Office  
Karen Reed  
John Powell  
C.S. 62/1  
Sept. 16, 1982

Douglas County  
Surveyors Office  
Stephen Flause  
John Pike  
Dec. 13, 1992  
C.S. File 64/35