

Douglas County Surveyor's Record of
Government Corners Renewed

T. 33 S. T. S. R. 5 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

John M. Powell
J. Brady
August & September, 1967
C. S. File No. 53/52

James W. Byron, Co. Surv.
J.M. Powell & Crew
March 19, 1968
C.S. File No. 49/112

~~Closing~~ Corner to Sections 34 and 35, T32-5W, *ONLY*
Found - Corner Stone 8 x 10 x 4, no markings. (See Ren. #7, T32-5)
10", now 14" Fir, N. 23½° E. 17.2 ft., shows good bark scribing,
plus good original face.
6" S. Pine, now 10" Snag, N. 51° W. 23.1 ft., shows good
scribing. No. trace of S.W. BT.
Set - Brass Cap at C.C. Mkd: County Surveyors T 32 S R 5 W
Office S 34 | S 35
1967 C C
T 33 S R 5 W
New BT: 10" D. Fir N. 20° W. 24.0 ft. mkd. T32S R5W S34 CC CS BT.
Note - This corner was renewed by B.B. Irving, 1930, & he bark
scribed N.E. Orig. BT. which has a good face.
Corner on steep eastside of hill

24

NOT A
CLOSING
CORNER

Section Corner to Sections 2 - 3 - 10 - 11.
Found - 1957 G. L. O. Brass Cap, properly marked.
Orig. 18" D. Fir, now 22" Snag, N. 36° E. 71.3 ft., shows good face.
Orig. 40" D. Fir, now 48" Stump, S. 82° E. 39.6 ft., opened
& shows scribe of "S".
Orig. 10", now 18" Stump, S. 21½° W. 19.1 ft., shows good face.
Orig. 14", now 18" Laurel, N. 54° W. 28.4 ft., show faint face.
Rescribed BT: 18" Laurel N. 54° W. 28.4 ft. mkd. T33S R5W S3 CS BT
New BT's: 16" W. Fir N. 5° E. 39.1 ft. mkd. T33S R5W S2 CS BT.
6" Cedar S. 23° E. 38.0 ft. mkd. T33S R5W S1 CS BT.
6" D. Fir S. 41° W. 33.6 ft. mkd. T33S R5W S10 CS BT.

25

Closing Corner to Sections 32 & 33, T32-5W.
Found - 60" Fir Stump N. 59° E. 22.1 ft. scribed CC T32S R5W S33 CS BT.
1" Axle at Corner set by Norman Price, 1953, See C.S. 41/184.
New BT's: 10" D. Fir N. 24° E. 20.6 ft. mkd. CC T32S R5W S33 CS BT.
12" D. Fir N. 1° W. 17.2 ft. mkd. CC T32S R5W S32 CS BT.

26

¼ Corner to Sections 2 and 11.
Found - Orig. 24", now 35" D. Fir, N. 27½° E. 35.0 ft., tree has been
opened but pitched over. Also bark scribed. See Ren. #5.
Orig. 24", now 38" D. Fir, S. 41° W. 29.0 ft., bark scribed.
5/8" Iron Rod at ¼ corner, not recorded.
Original Stone, "¼" on north side.
New BT: 6" D. Fir N. 52° E. 19.7 ft. mkd. ¼ S 2 CS BT.
Note - This corner lies west of creek, approx. 120.0 ft.

27

Corner to Sections 33 & 34 only, T32-5W.
Found - 1½" Iron Pipe at Section Corner, See Ren. #51, T32-5
30", now 50" D. Fir, S. 18° W. 19.1 ft., Orig. BT.
6" D. Fir, now stob, N. 40° E. 12.5 ft., scribe visible.
8" D. Fir, now stob, N. 8° W. 8.6 ft., scribe visible "R5W".
New BT's: 7" D. Fir N. 74° W. 5.9 ft. mkd. T32S R5W S33 CC CS BT.
14" Laurel N. 21° E. 16.0 ft. mkd. T32S R5W S34 CC CS BT.

28

MICROFILM TO HERE 10/67

Section Corner to Sec. 6, T33-5W & Sec. 1, T33-6W. only.
Found - 1½" Iron Pipe, unrecorded, but noted on M 12-51.
Orig. 10" Laurel, now rotten, S. 38° E. 35.6 ft., scribe found, "W3"
on chip.
10" Laurel, now hole, N. 88° W. 19.8 ft.
5" Laurel, now hole, N. 38° E. 19.8 ft., No trace of SW. BT.
New BT's: 11" D. Fir S. 65° W. 27.1 ft. mkd. T33S R6W S1 CS BT.
8" D. Fir S. 84° E. 15.3 ft. mkd. T33S R5W S6 CS BT.

29

Corner to Section 4, T33-5W. & Section 1, T33-6W.