

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 33 S. T. S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Byron & John M. Powell  
& Crew  
March 19, 1968  
C. S. File No. 49/112

Robert M. Thompson  
For: A. Mohr & A. Wells  
Nov. 15, 1971  
C.S. 55/236 M 44 - 38

Ronald A. Brandt  
For: Robert Dollar Co.  
C.S. File 55/294  
Map File M 49 @ 21

*Ed 8/90  
M110-48*

MARCH 71

JAN. 1972

Section Corner to Sec. 6, T33-5W. & Sec. 1, T33-6W only. 41  
Found - 1 1/2" Iron Pipe, unrecorded, but noted on M 12-51.  
Orig. 10" Laurel, now rotten, S.38°E. 35.6 ft., scribe found,  
10" Laurel, now hole, N.88°W. 19.8 ft. ("W3" on chip.)  
5" Laurel, now hole, N.38°E. 19.8 ft.  
No trace of SW, BT.  
New BT's: 11" D. Fir S.65°W. 27.1 ft. mkd. T33S R6W S1 CS BT.  
8" D. Fir S.84°E. 15.3 ft. mkd. T33S R5W S6 CS BT.

1/4 Corner to Section 6, T33-5W. & Section 1, T33-6W. 42  
Found - Orig. 14" B. Oak, now stump, S.34°W. (Rec. S.32W) 31.7 ft.,  
opened for scribe "BT".  
Orig. 12", now 23" B. Oak, S.60°E. 8.6 ft., shows scar.  
Set - Brass Cap at Cor. MKd: County Surveyor's Doug. Co.  
Office R T 33 S R  
1968 6 1/4 S 1 S 6 5  
W Jos. Co. W  
New BT: 11" D. Fir S.31°W. 24.3 ft. mkd. 1/4 S 1 CS BT.  
Reblzd. & Rescbd: 23" B. Oak S.60°E. 8.6 ft. mkd. 1/4 S 6 CS BT.  
Note - Corner lies approx. 35.0 ft. S. of ridge top, ridge running E-W.

Section Corner to Sec. 31, T32-5W. & Sec. 36, T32-6W. 43  
Found - 1 1/4" Axle at Corner & Large Fir Stump S.37°W. 45.4 ft. - See M 12-51  
(Revisited this corner in March 19, 1968 & find call to creek to west  
checks record. Also find now 23" Laurel, center rotted,  
checks record for N.E. BT. & stump hole that check record  
for N.W. BT. We open "new NW. R. Fir BT. & find scribe RE3024.  
New BT's. as scribed by R.E.3024: 8" R. Fir N.3 1/2°W. 15.4 ft.  
40" R. Fir N.7°E. 42.0 ft.

South 1/4 Corner to Section 35 only, T32-6W. 44  
Set - 1 1/2" I. Pipe, scribe "1/4 S 35 BT" on:  
14" D. Fir N. 77° E. 54.0 feet.  
14" D. Fir S. 11° W. 40.1 feet.

Closing Corner to Sections 34 & 35 only, T32-6W. 45  
Corner not found  
Set 1 1/2" I. Pipe, scribe "CC S 34 (& 35) BT" on:  
14" D. Fir N. 78° W. 15.5 feet  
10" D. Fir N. 82° E. 29.5 feet

North 1/4, Section 2 (33-6) 46  
Set 1"x36" I. rod 4" high from which bears -  
14.1" D. Fir, S.25°44'W. 18.68 ft. mkd. 1/4 S2 PS841 B.T.  
13.4" D. Fir, S.44°39'E. 28.50 ft. mkd. 1/4 S2 PS841 B.T.  
Also an old D. Fir Stump showing evidence of early corner search  
bears S.28°23'E. 44.0' from the corner as set, however,  
compared with the original B.T. (bearing from the corner a  
20" D. fir, S.21° E. 26.4') the corner would be placed = 11.45'  
East and 14.06' South of the corner as established.

Sec. Corner, Sec. 2 - 3 (33-6) 47  
Set 1" I. rod 4" high from which bears -  
7.5" Madrone, South, 9.10 ft. mkd. S2 33-6 PS841 B.T.  
6.8" D. Fir S.87°02'W. 38.08 ft. mkd. S 3 33-6 PS841 B.T.  
and fenceline is 1.5' No. of I. rod.

North 1/4, Sec. 3 (33-6) 48  
Set 1"x36" I. rod 12" deep in Sether field from which bears -  
1"x36" I. rod 4" high, N.46°55'34" E. 63.90 ft.  
1"x36" I. rod 4" high, N.45°47'26" W. 49.59 ft. both  
Set in fence line.  
1 1/2" I. Pipe (CS 42/327) N.89°31'26"W. 196.15 ft.  
fence line 38.50 ft. No. of I. rod at corner.

RECORDED & INDEXED NO. #56

May, 1973

May, 1973

May, 1973