

Douglas County Surveyor's Record of
Government Corners Renewed

T. 33 S. T.S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

Sec. Corner, Sec. 3 - 4 (33-6) Sether Field (SEE F.B. #97) **49**
Set 1"x60" I.rod, 12" deep from which bears - **P.30**
1"x36" I.rod 4" high, N.61°32'27"W., 22.96' at South
side of small cherry tree and
1"x36" I.rod 4" high, N.44°15'33"E. 56.26" at South
side of a cedar fence post and
1" I.Pipe 15" deep, N.89°30'59"W., 209.68' set by
Nelson, 1933.

May, 1973

1/4 Corner, Sec. 3 - 4 (33-6) in corner of Tunnel Road. **50**
Set 12"x1/2" sq. shank bridge spike, 1 1/16" Rd. head,
flush in asphalt surface from which bears -
1"x36" I.rod 4" high at SE side of 19.4" P.Pine,
N.33°59'W. 34.5' and
10" white oak, N.62°20'E., 29.75' mkd. 1/4 PS841 B.T.

Center 1/4 Corner Section 4. **51**
Set 1"x36" I.Rod 4" high from which bears -
20.5" D.Fir, N.80°09'39"W. 41.57 ft. mkd. C1/4, S4 PS
PS841 B.T.
13.0 D.Fir, N.8°19'21"E. 39.86 ft. mkd. C 1/4 S4
PS841 B.T.

Wenderoth's Corner, Ren. #20, C.S. 52/137, bears
East 0.56' and South 12.44 ft. (1"I.P & BT's.)

Section corner for Secs. 32 and 33 only, T.32-6. **FDOK PER LANG** **52**
M110-6 2-90
Found - A 1" iron pipe with brass cap attached at location determined
by Eppstein. Cap set by Powell (Ren. #30) marked "County
Surveyors Office" T32S R6W S32 S33 S5 T33S 1967.
An apple tree 8" now 15" with fragmentary scribing visible bears
N.81°E., 39.0 ft. (Rec. N.81°E., 39.6 ft.)
Power poles referred to in Ren. #30 have been replaced.
No new monument set.
New accessories: A 27" man hole collar marked "B.O." on South edge, center
punch bears S.63°W., 23.84 ft. (Note: bearing and distance to center
punch in "B.O" mark).

5/22/79

1/4 Corner for Section 4 only. (North) **53**
Found - A 1" I. P. flush with ground, set by Wenderoth as South Wit.
cor. per Ren. #17. No other monuments found. The 1/4 cor.
and west wit. corners set by Wenderoth have been washed
away by Cow Creek.
No original BTs or BTs per Renewal #6 found.
14" now 29" dia. Ash with double rotted out blaze facing 1/4
cor. position (Ren. #3) BT is also SW BT to west wit. cor.,
wrongly identified as a maple., with a double partially
healed blaze, scribing visible, facing position of Wenderoth
west wit. cor. (per Ren. #17)
NW BT per Ren. #3 gone.
SE BT to west wit. cor. per Ren. #17 down and washed out of
position.
Found BTs to south wit. cor. per Ren. #17:
36" now 43" dia. maple with a fully healed single blaze bears
S.24°06'E., 78.0 ft. (rec. S.24°06'E., 76.5 ft. to face).
36" now 36" dia. I. cedar with a fully healed single blaze
bears S.58°05'W., 86.2 ft. (Rec. S.58°05'W., 84.4 ft. to face).
Set - Computed N 1/4 cor. S. 4 T.33S., R.6W., as perpetuated by
Eppstein and Wenderoth. As evidenced by South wit. cor.
(Ren. No. 17) and Ash (SW BT Ren.No3) distance to Ash appears
to be a face measurement. New West wit. cor. placed on a line
between S 1/4 S33 T32S R6W and computed position of N 1/4 S4
T33S R6W. A DCSSO brass cap protrudes 4" above ground. Cap
stamped "Douglas County Surveyors

T33S East
W.C. to Cor
1/4 S4 70.0 ft.

Only
R6W
1986

Ronald A. Brandt
For: Robert Dollar Co.
Jan. - May, 1973
C.S. 55/294 Map File M 49 - 21

Gary Langlit
L.E. Monrean
P. Earle - S Flaus
Doug. Co. Surveyors
Office
May 22, 1979
C.S. 60/24

Douglas County Surveyors Office
Randall Smith - Stephen J. Flaus
May 23, 1986
C.S. 62/34

RENEWED SECTION CORNER NO. 55