

CS 39/194  
ATTACHED ARE COPIES OF SELECT PAGES THAT REFER TO  
FD/SET GOVERNMENT CORNERS  
CS FILE CONTAINS MORE INFORMATION

De Grath Road  
SECS 5 & 6 T.29-7W.  
Sept 1948

BEN B. IRVING  
NE RICHARDSON  
MILO GODFREY

CS 39/194



Sta	Dist.	Defl. &	C.C.	M.C.
C				236 <sup>3</sup>
	227 <sup>8</sup>			-15°24'
			571 <sup>1</sup> / <sub>4</sub> E	96410-
B.		36°24'		
		18°12'R		
	267 <sup>4</sup>			270 <sup>5</sup>
				-8°38'
			589 <sup>3</sup> / <sub>4</sub> E	98867-
A.		14°45'		
		7°22'30"L		
	185 <sup>8</sup>			1869
				-6°09'
			582 <sup>1</sup> / <sub>2</sub> E	94424-
Bens			582 <sup>1</sup> / <sub>2</sub> E	
1/4 Cor				

x on rock -

Fd Bens 1/4 Cor <sup>32</sup>/<sub>5</sub> T28 S - RTW  
T29 S RTW

Old Oak & Fir B.T.s O.K

Fir Bearing Dist

Old Laurel bears 552°30'E

Dist OK.

Set Fir stake for temp Cor.

Found Ben's stake about  
60 ft S. of orig loc.

Grid  
31/32  
6/5

40<sup>H</sup>

588°E

~~520°E~~

Sec 60  
31/32  
6/5  
Stewart

71°54' R

26<sup>7</sup>-L

306°

-10°59'

321<sup>z</sup>

NNE

19

20°35'

10°17'-30' R

287<sup>5</sup>

-24°28'

261<sup>z</sup>

N 10°30' E

18

23°28'

11°44' R

6x8x20' Rock being flat N on side  
set on end & new mound of rock



98168

Fd sandstone 20" x 6" x 4"  
in Md of Rock -

2 B.T.S

- N 13° W

60" Fir bears N 15 W - 195

Mkd S31-LSBT

91020

E 50° 8' W

48" Fir bears S 50 W - 212

B.T. legible

S. File No. 391194

5/15/59

Laurel BT  
BT legible  
Broken off  
& rotting



69°55'  
21°10'  
11°



48" Fir  
DBT  
Down  
scr/legible

Maple BT down  
under log.

DBT 54°W  
Laurel down  
scribe mks legible

Oak 543°W  
down & rotting

New BT 30" Fir  
583°E 78°  
R 5°27'

6" Fir 580°W 21°E  
R 168°30'


8" Fir 520°W 38°E  
R 110°10'

DBT 528°E  
Broken off  
Blaze & post  
scribe mks  
visible

Fir N 52°W 52°  
Standing  
blaze not changed

Laurel N 15°E  
66' gone  
probably under  
leaf

24" Fir N 32°E  
60°SE  
- 15°56' 30°  
L 63'



8" Fir  
38°  
38°

CS FILE FOLDER

CONTAINS

MORE

INFORMATION