



ALL B.T.'S FOUND EXCEPT LAUREL
N 25° E, 39 LKS. (THIS WAS DOWN
& ROTTED) ORIG. SEC. COR. POST
GONE, SO IT WAS REESTABLISHED
FROM EXISTING BEARING TREES.

T.R.E.

DESCRIPTION OF BEGINNING AT A
FROM THE ONE QU
29 AND 32 IN T
IN THE STATE OF
1616.16'; THENCE IN
THE SECTION LINE
IN THE ABOVE M.
WHICH IS LOCATE
SECTION CORNER
29 IN AFORESAID

SURVEY PROCEDURE
THE TRANSMIS.
SECTION CORNER
AND CHAIN DIST.
SOLAR OBSERVATI
MINATION TRIANG
AND LARGE TRE
NOTES WERE U
STATIONS ON ST
MINED BY STADI
COVERING THE S
THE HOME OFF
COMPANY.

OLD CEDAR POST FOUND.
B.T. TO NORTH DESTROYED
BY FIRE; B.T. TO SOUTH
PARTIALLY DEFACED.
South B.T. fallen
for line clearing.
1" iron pin driven
flush with the ground
at the location of
the cedar post.
1 1/2" x 45" iron pin
driven into ground
with 9" exposed.
The two Iron pins
are side by side.
(old cedar post
remains)

T.R.E.

FILED
RECEIVED
NOV 20 1950
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

T.R. Eslinger
L.S. #268
The California Oregon
Power Co.
Nov. 20, 1950