

Re-established corner.

$\frac{1}{4}$ cor Secs 6-7, T22S, R10W.

Fd Maple B.T. (now 24")
N57°E, 17 lks.

Set $\frac{1}{2}$ " Iron Bolt for
corner. (in Hwy R/W -
 $\frac{1}{2}$ & driveway leading to
stock pile)

B.I. & scribe N.B.T.

20" Maple, N8°W, 142 $\frac{1}{2}$ ft.

Marked $\frac{1}{4}$ 56 - B.T. copper
tag on tree - R.E. 2741

DOUGLAS COUNTY SURVEYOR
GREGORY
MAY 1, 1962

RECEIVED

