

CORNERS RENEWED IN TWP 29 S, R 4 W

Done for Patrick Lumber Co.

by Robert M Thompson, R. E. No. 3683

At Sec. Cor. $\frac{1}{16}$ I find 24" stunted D. Fir which U.S. notes call "Redwood", S57 $\frac{1}{2}$ °W, 43 ft. Find Scribe "5W, S1(2)" (2 Rotted out). Other B.T.'s burnt out.

To Renew, I set 6x10x12 Conglomerate stone.
I Scribe new B.T.'s: 40" D. Fir, S75°30'W, 46.0 ft.
14" I. Ced, N23°40'W, 36.4 ft.
40" D. Fir, N88°40'E, 57.2 ft.
17" I. Ced, S34°20'E, 21.2 ft. (Yel tag)

This cor. falls 6'E of Little Lick Cr., & Appr. 120' E of old logging Rd.

Renewed: June 5, 1958 by R.M. Thompson
L. Washburn Jr.
H. Hubbard

At $\frac{1}{4}$ Cor. $\frac{6}{7}$, I find 10" Fir, S60°W, 16 $\frac{1}{2}$ ft, (Now a 26" stump, Chopping into it's ^{long} butt I find "1 S" scribed. Other B.T. burnt out, stump hole evident

To Renew, I set $\frac{1}{2}$ " I.P.
I scribe new B.T.'s: 20" Madr. S40°20'E, 17.8 ft.
12" Madr. N 5°E, 21.0 ft.

Renewed: Same party as above

#142
At $\frac{1}{4}$ Cor. $\frac{1}{16}$, Being unable to find W $\frac{1}{4}$ Cor Sec. 6 After diligent search, I run Blank West Sec. Line. I find total distance of 5180.0 ft. At Midpoint on True Line, I set $\frac{3}{4}$ " I.P.

I Scribe: 15" D. Fir, S51°E, 31.0 ft
6" D. Fir, S78°30W, 44.0 ft

Renewed: June 11, 1958 by same party as above.

SW $\frac{1}{16}$ Cor. Bet. $\frac{6}{7}$, I run Blank line bet. SW cor. & South $\frac{1}{4}$ Cor. Sec. 6, I find Dist. of 2560.2ft. I set $\frac{1}{16}$ Cor. at Mid-point on True Line.

Set $\frac{1}{2}$ " I.P., Scribe: 20" D. Fir, N58°20'W, 30.2 ft
18" D. Fir, S 6°40'W, 18.5 ft

Set June 12, 1958 by same party as above.