

Claude Kerr Cruising and Engineering Service

REGISTERED PROFESSIONAL ENGINEER

Real Estate

PHONE ~~2-0754~~ 2108 W. ~~2420~~ FOOTHILL DRIVE
OR 2-1722 ROSEBURG, OREGON

Sept. 29, 1956

County Surveyor
County Courthouse
Roseburg, Oregon

Dear Sir:

I recently reset the following corners in Township 28 South, Range 3 West:

1. The corner for Sections 4, 5, 8, & 9.
I found only one original BT, now a 46" D. Fir, bearing S. 17° E. for 44 Lks.
I chopped in and found the old scribe marking. I rescribed this tree with S9BT and used it to reset the corner stake, a 4"x4", x 4' cedar stake marked S4, S5, S8 and S9.
I marked a new BT - a 42" D. Fir bearing N 39° E. for 50.7 feet, marked S4BT.
2. Reset a 3"x4"x4' cedar stake for the 1/4 corner for Sections 5 and 8.
Found one original BT, now an 18" maple, bearing N 10° W. for 3 Lks. I chopped in the old face and found the old marking, and then rescribed the outside with 1/4S5;
Marked a new BT - a 10" W. Fir, bearing S. 17° W. for 19.4 feet and scribed S 1/4 8BT on the face.

Yours truly,

Claude Kerr
Claude Kerr

FILED
RECEIVED

OCT 2 1956

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 42/91