

Section corner recovery

Section corner to Sections  
25, 26, 35 & 36  
Township 30 South Range 8 West

Set 5/8" pipe for section  
corner from existing bearing  
trees which are in good  
condition, from which bears,

A fir, 24" N 36° E 49.5'

Old bearing tree

A fir, 20" S 60° E 28.4'

Old bearing tree

B. L. M. tag.

A white fir, 8" S 57° 15' E

41.5' scribed " S 35 BT "

New bearing tree

October 29, 1956

R. H. Gee

Norman S. Walker

*R. H. Gee*