

Renewed the $\frac{1}{4}$ corner between sections 4 and 9 T31S, R8W W1, from old witness trees. The 12" chinquapin which bears N72°W 39 links now being a broken off stump and the 12" chinquapin which bears S22°W 19 links being a stump hole, with the uprooted stump lying near

set 4" Hemlock post 4 feet long for the corner and scribed 2 new trees.

A Fir 16" in diam. N18°E 25.8 feet

Marked $\frac{1}{4}$ T31S, R8W, Sec 4 2807 BT

This tree has a cruiser mark ∇ (Gilbert)

A Fir 5" in diam. S56°W 15 feet

marked $\frac{1}{4}$ T31S, R8W 59

Dorwin Powell

Wayland Oilar

Bob Carter

Bud

1/21/58

Richard C. Grant