

RENEW  $\frac{1}{4}$  COR.  $3\frac{1}{2}$  T265 R3 W

FD - 12" STONE WITH CHISELED +  
ON TOP 18" UNDER ROAD FILL AT  
COR. THE NW BT CHECKS FOR  
BEARING & DST. BARK SCRIBED  $\frac{1}{4}$ S  
(NOW 48" FIR) ORIG. ALSO FD. 48" FIR  
60° E 42.8' STANDING BUT BARK IS  
ROTTED NO SCRIBING FD

SET BRASS CAP AT COR.  
& OVER COR. STONE MKD.  $\frac{1}{4}$ S  
 $3\frac{1}{2}$  T265 R3 W. COUNTY SURVEYORS  
OFFICE 1957.

RE BARK SCRIBED N.W. B.T.  
 $\frac{1}{4}$ S 3 CS BT. (N45°W 33.0')

BLAZED & SCRIBED 12" CEDAR  
56.8° E 36.8'  $\frac{1}{4}$ S 2 CS BT.

J. B.

J. F.

APRIL 2-57

VAR 20  $\frac{1}{2}$ °

C. S. File No. 47/11