

RENEW $\frac{1413}{2324}$ T29S R9W

FOUND - $3/4$ " I.P. AT COR. AND

ALL BTS. THE SW IS STANDING HAS
BEEN DRIVEN ~~DOWN~~ YEARS AGO NO SCRIBING

VISIBLE. BT WAS PROBABLY BARK
SCRIBED. THE NE & SE SHOW BARK
SCRIBING. THE NW BT HAS OLD BLAZE
-UNDER.

THE NW SE & NE BTS DOWN
ALL FOUR BTS CHECK FIR BEARING
& DIST

SET BRASS CAP AT COR. MVD

SEC COR $\frac{1413}{2324}$ T29S R9W

COUNTY SURVEYORS OFFICE 1957.

FROM WHICH 12" W. FIR BEARS

S 58° E 26' SCRIBED S 24 T29S R9W

CS BT

12" W. FIR BEARS S 70° W 22.8'

SCRIBED S 23 T29S R9W CS BT

10" CEDAR BEARS N 9° E 57.4'

SCRIBED S 13 T29S R9W CS BT.

12" W. FIR BEAR N 56° W 62.8'

SCRIBED S 14 T29S R9W - CS BT

APRIL 8-57

J. B.

M. G. J. F.

CS 97/173-2