

1/4 COR. SECS $\frac{4}{9}$ T 28 S R 6 W

SET FROM 20" BACK OAK S 54° E 128 1/2 FT
TREE NOW 40" DIAM. - HAS BEEN CHOPPED
OPEN SEVERAL YEARS AGO - FACE AND
SCRIBE MARKS (1/4 S BT) PLAINLY VISIBLE
TREE ALIVE & STANDING - APPARENTLY IN
GOOD CONDITON, CORNER FALLS IN FENCE
CORNER - FENCES E., W. & SOUTH.

AT BEARING & DIST. FOR OTHER B.T. -
(N 57 1/2° E 175 FT.) FOUND UPROOTED OAK
STUMP - FACE DOWN, AS IT WAS TOO HEAVY
TO MOVE COULD NOT CHECK FOR SCRIBING,
BUT ASSUME IT TO HAVE BEEN THE OTHER B.T.

AT COR. SET IRON PIPE WITH BRASS CAP
STAMPED "COUNTY SURVEYORS OFFICE - 1957

T 28 S R 6 W 1/4 S $\frac{4}{9}$

AND MARKED NEW TREES AS FOLLOWS:

17" DOUGLAS FIR N 38° E 37 1/2 FT.
SCRIBED 1/4 S 4 CS BT

18" DOUGLAS FIR S 7° E 27 1/2 FT.
SCRIBED 1/4 S 9 CS BT

JUNE 27, 1957

M. GODFREY
J. FEE

REGISTERED
OREGON
LAND SURVEYOR

Fred M. Darby

MAY 7, 1954
FRED M. DARBY
320

C. S. File No. 47/196