

RENEW SEC. COR.  $\frac{1615}{21}$   $\frac{22}{22}$  T 285 R 8W

FOUND - ORIG. SE. BT NOW 36"  
SMAG THIS TREE WAS BARK SCRIBED  
BARK WITH SCRIBING "R" LAYING  
ON GROUND AT BASE OF TREE.  
ALSO I FIND EVIDENCE OF FIR  
TREE AT RECORD DITCH BEARING  
FOR S.W. ORIG. B.T. I CAN FIND NO  
EVIDENCE OF NE ORIG. BT NOR ON  
ORIG. BT (WHICH WOULD FALL IN AT  
ROAD.

SET BRASS CAP MKD  $\frac{1515}{21}$  T 285  
R 8W COUNTY SURVEYORS  
OFFICE 1957

14" W. FIR BEARS N 82° W 46.2 FT,  
SCRIBED T 288 R 8W S 16 CS. BT.

30" R. FIR BEARS S 47° W 39.0'  
SCRIBED S 21 T 285 R 8W CS BT

THIS TREE DAMAGED SEVERELY  
15" W. FIR BEARS N 86° W 42.0'  
SCRIBED S 16 T 285 R 8W CS BT  
WILL PROBABLY DIE

10" R. FIR BEARS N 73° E 60.0'  
SCRIBED S 15 T 285 R 8W CS. BT

26" HEMLOCK BEARS S 21° E 39.5'  
SCRIBED S 22 T 285 R 8W CS BT

VAR. 20 1/2

$\frac{1515}{21}$  T 285  
R 8W  
CS. BT

DIETZGEN NO. 3855-6