

✓ R9W R8W
 RENEW $\frac{2530}{3631}$ T 275

FOUND - ORIG. BT
 N33°30' E 27.1' FOUND BT "BARK
 SCRIBED IN PARTS OF OTHER SCRIBES MRS.
 FOUND ORIG. 24" CEDAR "NOV 32"
 N20°W 27.1' SHOWS OLD BARK - ROTTED
 IN SCRIBING FR ALSO TO BASE OF
 STUMP OF 2" HEMLOCK S 20°30' E
 27.7' S.W. ORIG. BT NOT FOUND
 IN ROADWAY.

NOTE - THIS COR WAS REVEALED
 ABOUT 40 YEARS AGO BUT NOT OR
 RECORDED IN OUR OFFICE MAY BE
 RECORDED IN COOS CO. I FIND 18"
 CEDAR (OPEY FACE) SCRIBED T
 275 R9W S31 BT. BEARS S80° E
 I ADD SCRIBING TO THIS BT DC3 BT

SET BRASS CAP AT COR. MKD
 D COUNTY SURVEYORS OFFICE 1957
 R9W R9W
 $\frac{2530}{3631}$ T 275
 3631 0
 0.00.

NEW BTs.
 32" CEDAR N40°W 27.1' SCRIBED
 T 275 R9W S 29 DC3 BT.
 52" CEDAR STUMP S33W 52 SCRIBED
 T 275 R9W O 36 DC3 BT.

RESCRIBED REVEALED CEDAR
 SEE NOTE ABOVE S80° E 10.5'
 RESCRIBED 5 1/2" FIR N33°30' E
 27.1' T 275 R9W S30 DC3 BT
 (BARK SCRIBED)

✓ JULY 18-57
 VAR 204° T.B.
 N.G.

DIETZGEN NO. 385-6