

T 28 S R 8 W
✓ 1/4 COR. SEC'S 34*35

FOUND 24" W. OAK S 51° E 35 FT.
HAS BEEN CHOPPED OUT SEVERAL YEARS
AGO. FACE IS EXPOSED AND BADLY
ROTTED BUT SOME SCRIBING IS STILL
VISIBLE - I COULD MAKE OUT A "T"
A "3" & A "5" ALONG WITH FRAGMENTS
OF OTHER LETTERS & NUMBERS (NOT
LEGIBLE)

FOUND 36" W. OAK S 50° E 99 FT.
BOTH UPPER & LOWER FALES ARE
EXPOSED BUT SO BADLY ROTTED NO
TRACE OF SCRIBING CAN BE SEEN
NO TRACE REMAINS OF OTHER B.T.'S
AT COR. POINT, WHICH LIES 2 FT. WEST
OF A FENCE COR., SET IRON PIPE WITH
BRASS CAP STAMPED "COUNTY SURVEYOR'S
OFFICE, 1957, T 28 S R 8 W,
1/4 S 34 | 35

BLAZE & SCRIBE 2 NEW TREES
13" CEDAR BEARS S 73° E 31 FT.
SCRIBED "1/4 S 35 CS BT"

8" WHITE OAK BEARS S 80° W 6 1/4 FT.

SCRIBED "1/4 S 34 CS BT"
OREGON
LAND SURVEYOR, 1957

M. E. GODFREY

JAMES W. BYSON FEE

NOV. 6, 1958
JAMES W. BYSON

303 C. S. File No. 49/5-12 ✓